



TRUESDELL EC LEAD WATER TEST RESULTS



Initial Filter Test After Installation

Less than 1 ppb - Device Returned to Service											
	Building Location: Building Name	Water Source ID	Date Analyzed	Floor	Device Type	Device Location		1st Draw - Sample ID	Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	Final Result - 2nd Draw (ppb)
1	TRUESDELL EDUCATIONAL CAMPUS	WS- 001010	12/24/2016	1	Combo Faucet	In classroom 100	Left	FT-122016-001010-A	< 1	FT-122016-001010-B	< 1
2	TRUESDELL EDUCATIONAL CAMPUS	WS- 001013	12/24/2016	1	Combo Faucet	In classroom 101	Left	FT-122016-001013-A	< 1	FT-122016-001013-B	< 1
3	TRUESDELL EDUCATIONAL CAMPUS	WS- 001021	12/24/2016	2	Combo Faucet	In classroom 217	Left	FT-122016-001021-A	< 1	FT-122016-001021-B	< 1
4	TRUESDELL EDUCATIONAL CAMPUS	WS- 001023	12/24/2016	2	Combo Faucet	In classroom 216	Left	FT-122016-001023-A	< 1	FT-122016-001023-B	< 1

Greater than 1 ppb - Devices Shut Off and Corrective Action Taken											
1	TRUESDELL EDUCATIONAL CAMPUS	WS- 000990	12/24/2016	1	Classroom Faucet	In classroom 103		FT-122016-000990-A	2.6	FT-122016-000990-B	< 1
2	TRUESDELL EDUCATIONAL CAMPUS	WS- 000991	12/24/2016	1	Combo Faucet	in classroom 115		FT-122016-000991-A	1.7	FT-122016-000991-B	< 1
3	TRUESDELL EDUCATIONAL CAMPUS	WS- 000992	12/24/2016	1	Combo Faucet	In classroom 114		FT-122016-000992-A	1.2	FT-122016-000992-B	< 1
4	TRUESDELL EDUCATIONAL CAMPUS	WS- 001016	12/24/2016	2	Combo Faucet	In classroom 200	Left	FT-122016-001016-A	1.9	FT-122016-001016-B	< 1
5	TRUESDELL EDUCATIONAL CAMPUS	WS- 001019	12/24/2016	2	Combo Faucet	In classroom 201	Left	FT-122016-001019-A	1.7	FT-122016-001019-B	< 1

First Filter Re-Test (After Filter and Plumbing Check with Aerator Replacement)

Greater than 1 ppb - Devices Remain Shut off, Continued Remediation											
1	TRUESDELL EDUCATIONAL CAMPUS	WS- 000990	1/25/2017	1	Classroom Faucet	In classroom 103		FT-122016-000990-A	1.7	FT-122016-000990-B	< 1
2	TRUESDELL EDUCATIONAL CAMPUS	WS- 000991	1/25/2017	1	Combo Faucet	in classroom 115		FT-122016-000991-A	1.7	FT-122016-000991-B	< 1
3	TRUESDELL EDUCATIONAL CAMPUS	WS- 000992	1/25/2017	1	Combo Faucet	In classroom 114		FT-122016-000992-A	2.3	FT-122016-000992-B	< 1
4	TRUESDELL EDUCATIONAL CAMPUS	WS- 001016	1/25/2017	2	Combo Faucet	In classroom 200	Left	FT-122016-001016-A	1.5	FT-122016-001016-B	< 1
5	TRUESDELL EDUCATIONAL CAMPUS	WS- 001019	1/25/2017	2	Combo Faucet	In classroom 201	Left	FT-122016-001019-A	2.6	FT-122016-001019-B	< 1

Second Filter Re-Test (After Device Replacement)

Less than 1 ppb - Device Returned to Service											
1	TRUESDELL EDUCATIONAL CAMPUS	WS- 000990	4/7/2017	1	Classroom Faucet	In classroom 103		FT-122016-000990-A	< 1	FT-122016-000990-B	< 1
2	TRUESDELL EDUCATIONAL CAMPUS	WS- 000991	4/7/2017	1	Combo Faucet	in classroom 115		FT-122016-000991-A	< 1	FT-122016-000991-B	< 1
3	TRUESDELL EDUCATIONAL CAMPUS	WS- 000992	4/7/2017	1	Combo Faucet	In classroom 114		FT-122016-000992-A	< 1	FT-122016-000992-B	< 1
4	TRUESDELL EDUCATIONAL CAMPUS	WS- 001019	4/7/2017	2	Combo Faucet	In classroom 201	Left	FT-122016-001019-A	< 1	FT-122016-001019-B	< 1

Greater than 1 ppb - Devices Remain Shut off, Continued Remediation											
1	TRUESDELL EDUCATIONAL CAMPUS	WS- 001016	1/25/2017	2	Combo Faucet	In classroom 200	Left	FT-122016-001016-A	3.9	FT-122016-001016-B	< 1

Note :

Filter re-tests are only performed to devices that have sampling results greater than 1 ppb