



# Turkey Thicket RC Lead in Water Test Results

## FY25 Filter Test

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 005503	4/19/2024	4/19/2025	1	Cooler	In pool area across from men's locker room	High	WF-04192024-005503	3/11/2025	FT-FY25-01082025-005503-A	<2	FT-FY25-01082025-005503-B	<2
WS- 005504	4/19/2024	4/19/2025	1	Cooler	In pool area across from men's locker room	Low	WF-04192024-005504	3/11/2025	FT-FY25-01082025-005504-A	<2	FT-FY25-01082025-005504-B	<2
WS- 005505	11/25/2024	11/25/2025	1	Food Prep Sink	In kitchen 104		WF-11252024-005505	3/11/2025	FT-FY25-01082025-005505-A	<2	FT-FY25-01082025-005505-B	<2
WS- 005506	11/25/2024	11/25/2025	1	Food Prep Sink	In multi-purpose room 102		WF-11252024-005506	3/11/2025	FT-FY25-01082025-005506-A	<2	FT-FY25-01082025-005506-B	<2
WS- 005507	4/19/2024	4/19/2025	1	Cooler	In lobby adjacent to weights and exercise room 118	High	WF-04192024-005507	3/11/2025	FT-FY25-01082025-005507-A	<2	FT-FY25-01082025-005507-B	<2
WS- 005508	4/19/2024	4/19/2025	1	Cooler	In lobby adjacent to weights and exercise room 119	Low	WF-04192024-005508	3/11/2025	FT-FY25-01082025-005508-A	<2	FT-FY25-01082025-005508-B	<2

Due to changes in water sampling analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.