



WHITTIER EC LEAD WATER TEST RESULTS



Initial Filter Test After Installation

Less than 1 ppb - Device Returned to Service										
	Building Location: Building Name	Water Source ID	Date Analyzed	Floor	Device Type	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	Final Result - 2nd Draw (ppb)
1	WHITTIER EDUCATIONAL CAMPUS	WS- 002338	12/29/2016	Floor	Bathroom	from the left	FT-122016-002338-A	< 1	FT-122016-002338-B	< 1
2	WHITTIER EDUCATIONAL CAMPUS	WS- 003732	12/29/2016	Floor	Classroom Faucet	In classroom 003	FT-122016-003732-A	< 1	FT-122016-003732-B	< 1
3	WHITTIER EDUCATIONAL CAMPUS	WS- 003720	12/29/2016	Floor	Bathroom	fourth from the left	FT-122016-003720-A	< 1	FT-122016-003720-B	< 1
4	WHITTIER EDUCATIONAL CAMPUS	WS- 002337	12/29/2016	Floor	Bathroom	fourth from the left	FT-122016-002337-A	< 1	FT-122016-002337-B	< 1
5	WHITTIER EDUCATIONAL CAMPUS	WS- 002341	12/29/2016	Floor	Bathroom	from the left	FT-122016-002341-A	< 1	FT-122016-002341-B	< 1
6	WHITTIER EDUCATIONAL CAMPUS	WS- 002340	12/29/2016	Floor	Bathroom	second from the left	FT-122016-002340-A	< 1	FT-122016-002340-B	< 1
7	WHITTIER EDUCATIONAL CAMPUS	WS- 003731	12/29/2016	Floor	Classroom Faucet	In classroom 007	FT-122016-003731-A	< 1	FT-122016-003731-B	< 1
8	WHITTIER EDUCATIONAL CAMPUS	WS- 003734	12/29/2016	Floor	Classroom Faucet	In classroom 006	FT-122016-003734-A	< 1	FT-122016-003734-B	< 1

Greater than 1 ppb - Devices Shut Off and Corrective Action Taken										
1	WHITTIER EDUCATIONAL CAMPUS	WS- 002334	12/29/2016	Floor	Bathroom	from the left	FT-122016-002334-A	2.5	FT-122016-002334-B	< 1
2	WHITTIER EDUCATIONAL CAMPUS	WS- 002332	12/29/2016	Floor	Bathroom	second from the left	FT-122016-002332-A	3	FT-122016-002332-B	< 1
3	WHITTIER EDUCATIONAL CAMPUS	WS- 003730	12/29/2016	Floor	Classroom Faucet	In classroom 002	FT-122016-003730-A	2.3	FT-122016-003730-B	< 1
4	WHITTIER EDUCATIONAL CAMPUS	WS- 003733	12/29/2016	Floor	Classroom Faucet	In classroom 004	FT-122016-003733-A	3.6	FT-122016-003733-B	< 1
5	WHITTIER EDUCATIONAL CAMPUS	WS- 002331	12/29/2016	Floor	Bathroom	from the left	FT-122016-002331-A	3.7	FT-122016-002331-B	< 1

First Filter Re-Test (After Filter and Plumbing Check with Aerator Replacement)

Less than 1 ppb - Device Returned to Service										
1	WHITTIER EDUCATIONAL CAMPUS	WS- 002334	1/25/2017	Floor	Bathroom	from the left	FT-122016-002334-A	< 1	FT-122016-002334-B	< 1
2	WHITTIER EDUCATIONAL CAMPUS	WS- 003733	1/25/2017	Floor	Classroom Faucet	In classroom 004	FT-122016-003733-A	< 1	FT-122016-003733-B	< 1

Greater than 1 ppb - Devices Remain Shut off, Continued Remediation										
1	WHITTIER EDUCATIONAL CAMPUS	WS- 002331	1/25/2017	Floor	Bathroom	from the left	FT-122016-002331-A	2.5	FT-122016-002331-B	< 1
2	WHITTIER EDUCATIONAL CAMPUS	WS- 002332	1/25/2017	Floor	Bathroom	second from the left	FT-122016-002332-A	2.4	FT-122016-002332-B	< 1
3	WHITTIER EDUCATIONAL CAMPUS	WS- 003730	1/25/2017	Floor	Classroom Faucet	In classroom 002	FT-122016-003730-A	1.6	FT-122016-003730-B	< 1

Second Filter Re-Test (After Device Replacement)

Less than 1 ppb - Device Returned to Service										
1	WHITTIER EDUCATIONAL CAMPUS	WS- 002331	4/7/2017	Floor	Bathroom	from the left	FT-122016-002331-A	< 1	FT-122016-002331-B	< 1
2	WHITTIER EDUCATIONAL CAMPUS	WS- 002332	4/7/2017	Floor	Bathroom	second from the left	FT-122016-002332-A	< 1	FT-122016-002332-B	< 1
3	WHITTIER EDUCATIONAL CAMPUS	WS- 003730	4/7/2017	Floor	Classroom Faucet	In classroom 002	FT-122016-003730-A	< 1	FT-122016-003730-B	< 1

Note :

Filter re-tests are only performed to devices that have sampling results greater than 1 ppb