



Wilson AC Lead in Water Test Results

FY22 Filter Test

| Less than 5ppb - Devices requiring no remediation | | | | | | | | | | | |
|---|-----------------------|------------------------|-------|----------------|--|---------------------|---------------|---------------------------|----------------------------------|---------------------------|----------------------------------|
| Record ID | Filter Installed Date | Filter Expiration Date | Floor | Device Type | Device Location | Water Filter's Name | Date Analyzed | 1st Draw - Sample ID | FT Final Result - 1st Draw (ppb) | 2nd Draw - Sample ID | FT Final Result - 2nd Draw (ppb) |
| WS- 012029 | 1/6/2022 | 1/6/2023 | 2 | Food Prep Sink | In recreation room 212 | WF-01062022-012029 | 2/13/2022 | FT-FY22-01182022-012029-A | <1 | FT-FY22-01182022-012029-B | <1 |
| WS- 012031 | 3/11/2021 | 3/11/2022 | 1 | Cooler | In hallway adjacent to room 113 High Left | WF-03112021-012031 | 2/13/2022 | FT-FY22-01182022-012031-A | <1 | FT-FY22-01182022-012031-B | <1 |
| WS- 012032 | 3/11/2021 | 3/11/2022 | 1 | Cooler | In hallway adjacent to room 114 Low Right | WF-03112021-012032 | 2/13/2022 | FT-FY22-01182022-012032-A | <1 | FT-FY22-01182022-012032-B | <1 |
| WS- 012033 | 3/11/2021 | 3/11/2022 | 1 | Cooler | In pool area High Left | WF-03112021-012033 | 2/13/2022 | FT-FY22-01182022-012033-A | <1 | FT-FY22-01182022-012033-B | <1 |
| WS- 012034 | 3/11/2021 | 3/11/2022 | 1 | Cooler | In pool area Low Right | WF-03112021-012034 | 2/13/2022 | FT-FY22-01182022-012034-A | <1 | FT-FY22-01182022-012034-B | <1 |
| WS- 012382 | 3/11/2021 | 3/11/2022 | 2 | Cooler | In hallway across from 219 spectator seating High Left | WF-03112021-012382 | 2/13/2022 | FT-FY22-01182022-012382-A | <1 | FT-FY22-01182022-012382-B | <1 |
| WS- 012383 | 3/11/2021 | 3/11/2022 | 2 | Cooler | In hallway across from 219 spectator seating Low Right | WF-03112021-012383 | 2/13/2022 | FT-FY22-01182022-012383-A | <1 | FT-FY22-01182022-012383-B | <1 |