



Arboretum RC Lead in Water Test Results

FY26 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 001235	2/13/2026	2/13/2027	1	Break Room	In room 101 cafeteria	WF-02132026-001235	4/2/2026	FT-FY26-03202026-001235-A	<2	FT-FY26-03202026-001235-B	<2
WS- 001236	2/13/2026	2/13/2027	1	Bottle Filler	In hallway adjacent to women's restroom	WF-02132026-001236	4/2/2026	FT-FY26-03202026-001236-A	<2	FT-FY26-03202026-001236-B	<2
WS- 001237	2/13/2026	2/13/2027	1	Cooler	In hallway adjacent to women's restroom High Left	WF-02132026-001237	4/2/2026	FT-FY26-03202026-001237-A	<2	FT-FY26-03202026-001237-B	<2

Due to changes in water sampling analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.