



Banneker Community Center Lead in Water Test Results

FY23 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 012655	12/21/2022	12/21/2023	1	Food Prep Sink	In kitchenette in gym	WF-12212022-012655	1/26/2023	FT-FY23-01092023-012655-A	<1	FT-FY23-01092023-012655-B	<1
WS- 012667	5/9/2022	5/9/2023	1	Cooler	In hallway adjacent to room 102 in lobby High Left	WF-05092022-012667	1/26/2023	FT-FY23-01092023-012667-A	<1	FT-FY23-01092023-012667-B	<1
WS- 012668	5/9/2022	5/9/2023	1	Cooler	In hallway adjacent to room 102 in lobby Low Right	WF-05092022-012668	1/26/2023	FT-FY23-01092023-012668-A	<1	FT-FY23-01092023-012668-B	<1
WS- 012669	5/9/2022	5/9/2023	1	Bottle Filler	In hallway adjacent to room 102 in lobby	WF-05092022-012669	1/26/2023	FT-FY23-01092023-012669-A	<1	FT-FY23-01092023-012669-B	<1
WS- 012670	5/9/2022	5/9/2023	Basement	Cooler	In hallway adjacent to men's locker room High Left	WF-05092022-012670	1/26/2023	FT-FY23-01092023-012670-A	<1	FT-FY23-01092023-012670-B	<1
WS- 012671	5/9/2022	5/9/2023	Basement	Cooler	In hallway adjacent to men's locker room Low Right	WF-05092022-012671	1/26/2023	FT-FY23-01092023-012671-A	<1	FT-FY23-01092023-012671-B	<1
WS- 012672	5/9/2022	5/9/2023	Basement	Bottle Filler	In hallway adjacent to men's locker room	WF-05092022-012672	1/26/2023	FT-FY23-01092023-012672-A	<1	FT-FY23-01092023-012672-B	<1