



Banneker CC Lead in Water Test Results

FY26 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 012655	11/13/2025	11/13/2026	1	Food Prep Sink	In kitchenette in gym	WF-11132025-012655	3/5/2026	FT-FY26-01282026-012655-A	<2	FT-FY26-01282026-012655-B	<2
WS- 012667	10/27/2025	10/27/2026	1	Cooler	In hallway adjacent to room 102 in lobby High Left	WF-10272025-012667	3/5/2026	FT-FY26-01282026-012667-A	<2	FT-FY26-01282026-012667-B	<2
WS- 012668	10/27/2025	10/27/2026	1	Cooler	In hallway adjacent to room 102 in lobby Low Right	WF-10272025-012668	3/5/2026	FT-FY26-01282026-012668-A	<2	FT-FY26-01282026-012668-B	<2
WS- 012669	10/27/2025	10/27/2026	1	Bottle Filler	In hallway adjacent to room 102 in lobby	WF-10272025-012669	3/5/2026	FT-FY26-01282026-012669-A	<2	FT-FY26-01282026-012669-B	<2
WS- 012670	4/7/2025	4/7/2026	Basement	Cooler	In hallway adjacent to men's locker room High Left	WF-04072025-012670	3/5/2026	FT-FY26-01282026-012670-A	<2	FT-FY26-01282026-012670-B	<2
WS- 012671	4/7/2025	4/7/2026	Basement	Cooler	In hallway adjacent to men's locker room Low Right	WF-04072025-012671	3/5/2026	FT-FY26-01282026-012671-A	<2	FT-FY26-01282026-012671-B	<2

Due to changes in water sampling analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.