



Bard HS Lead in Water Test Results

FY26 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
WS-016150	5/7/2025	5/7/2026	1	Bottle Filler	In hallway across from the gym	WF-05072025-016150	11/3/2025	FT-FY26-09302025-016150-A	<2	FT-FY26-09302025-016150-B	<2	
WS-016151	5/7/2025	5/7/2026	1	Cooler	In hallway across from the gym	High Left	WF-05072025-016151	11/3/2025	FT-FY26-09302025-016151-A	<2	FT-FY26-09302025-016151-B	<2
WS-016152	5/7/2025	5/7/2026	1	Cooler	In hallway across from the gym	Low Right	WF-05072025-016152	11/3/2025	FT-FY26-09302025-016152-A	<2	FT-FY26-09302025-016152-B	<2
WS-016154	5/7/2025	5/7/2026	1	Cooler	In gym	High Left	WF-05072025-016154	11/3/2025	FT-FY26-09302025-016154-A	<2	FT-FY26-09302025-016154-B	<2
WS-016155	5/7/2025	5/7/2026	1	Cooler	In gym	Low Right	WF-05072025-016155	11/3/2025	FT-FY26-09302025-016155-A	<2	FT-FY26-09302025-016155-B	<2
WS-016156	5/7/2025	5/7/2026	1	Bottle Filler	In hallway across from restrooms		WF-05072025-016156	11/3/2025	FT-FY26-09302025-016156-A	<2	FT-FY26-09302025-016156-B	<2
WS-016157	5/7/2025	5/7/2026	1	Cooler	In hallway across from restrooms	High Left	WF-05072025-016157	11/3/2025	FT-FY26-09302025-016157-A	<2	FT-FY26-09302025-016157-B	<2
WS-016158	5/7/2025	5/7/2026	1	Cooler	In hallway across from restrooms	Low Right	WF-05072025-016158	11/3/2025	FT-FY26-09302025-016158-A	<2	FT-FY26-09302025-016158-B	<2
WS-016160	5/7/2025	5/7/2026	1	Classroom Faucet	In instrument room A126		WF-05072025-016160	11/3/2025	FT-FY26-09302025-016160-A	<2	FT-FY26-09302025-016160-B	<2
WS-016162	5/7/2025	5/7/2026	1	Classroom Faucet	In choral room A125		WF-05072025-016162	11/3/2025	FT-FY26-09302025-016162-A	2.9	FT-FY26-09302025-016162-B	<2
WS-016163	5/7/2025	5/7/2026	1	Bottle Filler	In student dining area		WF-05072025-016163	11/3/2025	FT-FY26-09302025-016163-A	<2	FT-FY26-09302025-016163-B	<2
WS-016164	5/7/2025	5/7/2026	1	Cooler	In student dining area	High Left	WF-05072025-016164	11/3/2025	FT-FY26-09302025-016164-A	<2	FT-FY26-09302025-016164-B	<2
WS-016165	5/7/2025	5/7/2026	1	Cooler	In student dining area	Low Right	WF-05072025-016165	11/3/2025	FT-FY26-09302025-016165-A	<2	FT-FY26-09302025-016165-B	<2
WS-016169	5/7/2025	5/7/2026	1	Classroom Faucet	In parent center B139		WF-05072025-016169	11/3/2025	FT-FY26-09302025-016169-A	<2	FT-FY26-09302025-016169-B	<2
WS-016170	5/7/2025	5/7/2026	1	Bottle Filler	In hallway adjacent to A105		WF-05072025-016170	11/3/2025	FT-FY26-09302025-016170-A	<2	FT-FY26-09302025-016170-B	<2
WS-016171	5/7/2025	5/7/2026	1	Cooler	In hallway adjacent to A105	High Left	WF-05072025-016171	11/3/2025	FT-FY26-09302025-016171-A	<2	FT-FY26-09302025-016171-B	<2
WS-016172	5/7/2025	5/7/2026	1	Cooler	In hallway adjacent to A105	Low Right	WF-05072025-016172	11/3/2025	FT-FY26-09302025-016172-A	<2	FT-FY26-09302025-016172-B	<2
WS-016173	5/7/2025	5/7/2026	1	Health Suite	In treatment room A107D		WF-05072025-016173	11/3/2025	FT-FY26-09302025-016173-A	<2	FT-FY26-09302025-016173-B	<2
WS-016174	5/7/2025	5/7/2026	2	Bottle Filler	In hallway adjacent to B211		WF-05072025-016174	11/3/2025	FT-FY26-09302025-016174-A	<2	FT-FY26-09302025-016174-B	<2
WS-016175	5/7/2025	5/7/2026	2	Cooler	In hallway adjacent to B211	High Left	WF-05072025-016175	11/3/2025	FT-FY26-09302025-016175-A	<2	FT-FY26-09302025-016175-B	<2
WS-016176	5/7/2025	5/7/2026	2	Cooler	In hallway adjacent to B211	Low Right	WF-05072025-016176	11/3/2025	FT-FY26-09302025-016176-A	<2	FT-FY26-09302025-016176-B	<2
WS-016177	5/7/2025	5/7/2026	2	Break Room	In teacher collaboration B213		WF-05072025-016177	11/3/2025	FT-FY26-09302025-016177-A	<2	FT-FY26-09302025-016177-B	<2
WS-016179	5/7/2025	5/7/2026	2	Cooler	In hallway across from B223	High Left	WF-05072025-016179	11/3/2025	FT-FY26-09302025-016179-A	<2	FT-FY26-09302025-016179-B	<2
WS-016180	5/7/2025	5/7/2026	2	Cooler	In hallway across from B223	Low Right	WF-05072025-016180	11/3/2025	FT-FY26-09302025-016180-A	<2	FT-FY26-09302025-016180-B	<2
WS-016185	5/7/2025	5/7/2026	2	Break Room	In staff lounge B205		WF-05072025-016185	11/3/2025	FT-FY26-09302025-016185-A	<2	FT-FY26-09302025-016185-B	<2
WS-016186	5/7/2025	5/7/2026	2	Break Room	In lactation suite B207		WF-05072025-016186	11/3/2025	FT-FY26-09302025-016186-A	2.6	FT-FY26-09302025-016186-B	<2
WS-016190	5/7/2025	5/7/2026	3	Bottle Filler	In hallway across from B323		WF-05072025-016190	11/3/2025	FT-FY26-09302025-016190-A	<2	FT-FY26-09302025-016190-B	<2
WS-016191	5/7/2025	5/7/2026	3	Cooler	In hallway across from B323	High Left	WF-05072025-016191	11/3/2025	FT-FY26-09302025-016191-A	<2	FT-FY26-09302025-016191-B	<2
WS-016192	5/7/2025	5/7/2026	3	Cooler	In hallway across from B323	Low Right	WF-05072025-016192	11/3/2025	FT-FY26-09302025-016192-A	<2	FT-FY26-09302025-016192-B	<2
WS-016193	5/7/2025	5/7/2026	3	Break Room	In office/workroom B331A		WF-05072025-016193	11/3/2025	FT-FY26-09302025-016193-A	<2	FT-FY26-09302025-016193-B	<2
WS-016195	5/7/2025	5/7/2026	3	Break Room	In teacher collaboration B303		WF-05072025-016195	11/3/2025	FT-FY26-09302025-016195-A	<2	FT-FY26-09302025-016195-B	<2
WS-016196	5/7/2025	5/7/2026	4	Bottle Filler	In hallway adjacent to B411		WF-05072025-016196	11/3/2025	FT-FY26-09302025-016196-A	<2	FT-FY26-09302025-016196-B	<2
WS-016197	5/7/2025	5/7/2026	4	Cooler	In hallway adjacent to B411	High Left	WF-05072025-016197	11/3/2025	FT-FY26-09302025-016197-A	<2	FT-FY26-09302025-016197-B	<2
WS-016198	8/13/2025	8/13/2026	4	Cooler	In hallway adjacent to B411	Low Right	WF-08132025-016198	11/3/2025	FT-FY26-09302025-016198-A	<2	FT-FY26-09302025-016198-B	<2

WS-016199	5/7/2025	5/7/2026	4	Bottle Filler	In hallway across from B423	WF-05072025-016199	11/3/2025	FT-FY26-09302025-016199-A	<2	FT-FY26-09302025-016199-B	<2
WS-016200	5/7/2025	5/7/2026	4	Cooler	In hallway across from B423 High Left	WF-05072025-016200	11/3/2025	FT-FY26-09302025-016200-A	<2	FT-FY26-09302025-016200-B	<2
WS-016201	5/7/2025	5/7/2026	4	Cooler	In hallway across from B423 Low Right	WF-05072025-016201	11/3/2025	FT-FY26-09302025-016201-A	<2	FT-FY26-09302025-016201-B	<2
WS-016202	5/7/2025	5/7/2026	4	Classroom Faucet	In speech OT/PT office B424	WF-05072025-016202	11/3/2025	FT-FY26-09302025-016202-A	<2	FT-FY26-09302025-016202-B	<2
WS-016203	5/7/2025	5/7/2026	4	Break Room	In teacher collaboration B402	WF-05072025-016203	11/3/2025	FT-FY26-09302025-016203-A	<2	FT-FY26-09302025-016203-B	<2
WS-016204	5/7/2025	5/7/2026	4	Classroom Faucet	In speech OT/PT office B404	WF-05072025-016204	11/3/2025	FT-FY26-09302025-016204-A	<2	FT-FY26-09302025-016204-B	<2

Food Prep Sink

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS-016168	11/20/2024	11/20/2025	1	Food Prep Sink	In kitchen on island	WF-11202024-016168	11/3/2025	FT-FY26-09302025-016168-A	<2	FT-FY26-09302025-016168-B	<2

Due to changes in water sampling analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.