



# PARKVIEW ES LEAD WATER TEST RESULTS



## Initial Filter Test After Installation

	Building Location: Building Name	RECORD ID	Date Analyzed	Floor	Device Type	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	Final Result - 2nd Draw (ppb)
1	BRUCE - MONROE@PARKVIEW ES	WS- 003677	12/23/2016	1	Break Room	In staff lounge	FT-102016-003677-A	< 1	FT-102016-003677-B	< 1
2	BRUCE - MONROE@PARKVIEW ES	WS- 004562	12/23/2016	Ground Floor	Classroom Faucet	In classroom 024	FT-122016-004562-A	< 1	FT-122016-004562-B	< 1
3	BRUCE - MONROE@PARKVIEW ES	WS- 004560	12/23/2016	Ground Floor	Classroom Faucet	In classroom 022	FT-122016-004560-A	< 1	FT-122016-004560-B	< 1
4	BRUCE - MONROE@PARKVIEW ES	WS- 004561	12/23/2016	Ground Floor	Classroom Faucet	In classroom 021	FT-122016-004561-A	< 1	FT-122016-004561-B	< 1
5	BRUCE - MONROE@PARKVIEW ES	WS- 004565	12/23/2016	Ground Floor	Classroom Faucet	In classroom 006	FT-122016-004565-A	< 1	FT-122016-004565-B	< 1
6	BRUCE - MONROE@PARKVIEW ES	WS- 004564	12/23/2016	Ground Floor	Classroom Faucet	In classroom 007	FT-122016-004564-A	< 1	FT-122016-004564-B	< 1
7	BRUCE - MONROE@PARKVIEW ES	WS- 004563	12/23/2016	Ground Floor	Classroom Faucet	In classroom 008	FT-122016-004563-A	< 1	FT-122016-004563-B	< 1

Note :

Filter re-tests are only performed to devices that have sampling results greater than 1 ppb