



Eastern HS Lead in Water Test Results

FY26 Filter Test

Less than 5ppb - Devices requiring no remediation

| Record ID | Filter Installed Date | Filter Expiration Date | Floor | Device Type | Device Location | Water Filter's Name | Date Analyzed | 1st Draw - Sample ID | FT Final Result - 1st Draw (ppb) | 2nd Draw - Sample ID | FT Final Result - 2nd Draw (ppb) | |
|------------|-----------------------|------------------------|--------------|----------------|--|---------------------|--------------------|---------------------------|----------------------------------|---------------------------|----------------------------------|----|
| WS- 002033 | 11/6/2025 | 11/6/2026 | 1 | Bottle Filler | In hallway adjacent to room E124 | WF-11062025-002033 | 12/16/2025 | FT-FY26-12082025-002033-A | <2 | FT-FY26-12082025-002033-B | <2 | |
| WS- 002336 | 2/26/2025 | 2/26/2026 | 1 | Combo Fountain | In classroom W143 | Right | WF-02262025-002336 | 12/16/2025 | FT-FY26-12082025-002336-A | <2 | FT-FY26-12082025-002336-B | <2 |
| WS- 002342 | 2/26/2025 | 2/26/2026 | 1 | Break Room | In break room W143 | Left | WF-02262025-002342 | 12/16/2025 | FT-FY26-12082025-002342-A | <2 | FT-FY26-12082025-002342-B | <2 |
| WS- 002345 | 2/26/2025 | 2/26/2026 | 1 | Combo Fountain | In classroom W143 | Left | WF-02262025-002345 | 12/16/2025 | FT-FY26-12082025-002345-A | <2 | FT-FY26-12082025-002345-B | <2 |
| WS- 010709 | 2/26/2025 | 2/26/2026 | 1 | Health Suite | In health suite W130 | | WF-02262025-010709 | 12/16/2025 | FT-FY26-12082025-010709-A | <2 | FT-FY26-12082025-010709-B | <2 |
| WS- 010711 | 2/26/2025 | 2/26/2026 | 1 | Health Suite | In health suite in lab room W129 | | WF-02262025-010711 | 12/16/2025 | FT-FY26-12082025-010711-A | <2 | FT-FY26-12082025-010711-B | <2 |
| WS- 010712 | 2/26/2025 | 2/26/2026 | 1 | Health Suite | In health suite in exam room W128 | | WF-02262025-010712 | 12/16/2025 | FT-FY26-12082025-010712-A | <2 | FT-FY26-12082025-010712-B | <2 |
| WS- 010713 | 2/26/2025 | 2/26/2026 | 1 | Health Suite | In health suite W131 | | WF-02262025-010713 | 12/16/2025 | FT-FY26-12082025-010713-A | <2 | FT-FY26-12082025-010713-B | <2 |
| WS- 010714 | 2/26/2025 | 2/26/2026 | 1 | Health Suite | In health suite in exam room W134 | | WF-02262025-010714 | 12/16/2025 | FT-FY26-12082025-010714-A | <2 | FT-FY26-12082025-010714-B | <2 |
| WS- 010716 | 11/6/2025 | 11/6/2026 | 1 | Cooler | In hallway across from room W130 | | WF-11062025-010716 | 12/16/2025 | FT-FY26-12082025-010716-A | <2 | FT-FY26-12082025-010716-B | <2 |
| WS- 010717 | 11/6/2025 | 11/6/2026 | 1 | Bottle Filler | In hallway across from room W130 (bottle filler) | | WF-11062025-010717 | 12/16/2025 | FT-FY26-12082025-010717-A | <2 | FT-FY26-12082025-010717-B | <2 |
| WS- 010722 | 2/26/2025 | 2/26/2026 | Ground Floor | Cooler | In cafeteria | Low Right | WF-02262025-010722 | 12/16/2025 | FT-FY26-12082025-010722-A | <2 | FT-FY26-12082025-010722-B | <2 |
| WS- 010723 | 2/26/2025 | 2/26/2026 | Ground Floor | Cooler | In cafeteria | High Left | WF-02262025-010723 | 12/16/2025 | FT-FY26-12082025-010723-A | <2 | FT-FY26-12082025-010723-B | <2 |
| WS- 010727 | 2/26/2025 | 2/26/2026 | 1 | Break Room | In break room W110 | | WF-02262025-010727 | 12/16/2025 | FT-FY26-12082025-010727-A | <2 | FT-FY26-12082025-010727-B | <2 |
| WS- 010730 | 11/6/2025 | 11/6/2026 | 1 | Cooler | In hallway adjacent to room E124 | | WF-11062025-010730 | 12/16/2025 | FT-FY26-12082025-010730-A | <2 | FT-FY26-12082025-010730-B | <2 |
| WS- 010767 | 11/6/2025 | 11/6/2026 | 1 | Cooler | In hallway across from gym | Low Right | WF-11062025-010767 | 12/16/2025 | FT-FY26-12082025-010767-A | <2 | FT-FY26-12082025-010767-B | <2 |
| WS- 010768 | 2/26/2025 | 2/26/2026 | 2 | Cooler | In hallway across from room E218 | High Left | WF-02262025-010768 | 12/16/2025 | FT-FY26-12082025-010768-A | <2 | FT-FY26-12082025-010768-B | <2 |
| WS- 010769 | 2/26/2025 | 2/26/2026 | 2 | Cooler | In hallway across from room E218 | Low Right | WF-02262025-010769 | 12/16/2025 | FT-FY26-12082025-010769-A | <2 | FT-FY26-12082025-010769-B | <2 |
| WS- 010775 | 2/26/2025 | 2/26/2026 | 2 | Cooler | In hallway adjacent room E227 | | WF-02262025-010775 | 12/16/2025 | FT-FY26-12082025-010775-A | <2 | FT-FY26-12082025-010775-B | <2 |
| WS- 010783 | 2/26/2025 | 2/26/2026 | 2 | Cooler | In hallway across from room W212 | High Left | WF-02262025-010783 | 12/16/2025 | FT-FY26-12082025-010783-A | <2 | FT-FY26-12082025-010783-B | <2 |
| WS- 010784 | 2/26/2025 | 2/26/2026 | 2 | Cooler | In hallway across from room W212 | Low Right | WF-02262025-010784 | 12/16/2025 | FT-FY26-12082025-010784-A | <2 | FT-FY26-12082025-010784-B | <2 |
| WS- 010785 | 2/26/2025 | 2/26/2026 | 2 | Break Room | In break room W209 | | WF-02262025-010785 | 12/16/2025 | FT-FY26-12082025-010785-A | <2 | FT-FY26-12082025-010785-B | <2 |
| WS- 010788 | 2/26/2025 | 2/26/2026 | 2 | Break Room | In break room E211 | | WF-02262025-010788 | 12/16/2025 | FT-FY26-12082025-010788-A | <2 | FT-FY26-12082025-010788-B | <2 |
| WS- 010789 | 2/26/2025 | 2/26/2026 | 3 | Cooler | In hallway across from room E316 | Low Right | WF-02262025-010789 | 12/16/2025 | FT-FY26-12082025-010789-A | <2 | FT-FY26-12082025-010789-B | <2 |
| WS- 010790 | 2/26/2025 | 2/26/2026 | 3 | Cooler | In hallway across from room E316 | High Left | WF-02262025-010790 | 12/16/2025 | FT-FY26-12082025-010790-A | <2 | FT-FY26-12082025-010790-B | <2 |
| WS- 010793 | 2/26/2025 | 2/26/2026 | 3 | Cooler | In hallway across from room W311 | High Left | WF-02262025-010793 | 12/16/2025 | FT-FY26-12082025-010793-A | <2 | FT-FY26-12082025-010793-B | <2 |
| WS- 010794 | 2/26/2025 | 2/26/2026 | 3 | Cooler | In hallway across from room W311 | Low Right | WF-02262025-010794 | 12/16/2025 | FT-FY26-12082025-010794-A | <2 | FT-FY26-12082025-010794-B | <2 |
| WS- 010838 | 2/26/2025 | 2/26/2026 | 4 | Cooler | In hallway across from room W411 | Low Right | WF-02262025-010838 | 12/16/2025 | FT-FY26-12082025-010838-A | <2 | FT-FY26-12082025-010838-B | <2 |
| WS- 010839 | 2/26/2025 | 2/26/2026 | 4 | Cooler | In hallway across from room W411 | High Left | WF-02262025-010839 | 12/16/2025 | FT-FY26-12082025-010839-A | <2 | FT-FY26-12082025-010839-B | <2 |
| WS- 010965 | 2/26/2025 | 2/26/2026 | Basement | Cooler | In boys locker room | | WF-02262025-010965 | 12/16/2025 | FT-FY26-12082025-010965-A | <2 | FT-FY26-12082025-010965-B | <2 |
| WS- 011744 | 11/6/2025 | 11/6/2026 | 1 | Bottle Filler | In hallway across from gym | | WF-11062025-011744 | 12/16/2025 | FT-FY26-12082025-011744-A | <2 | FT-FY26-12082025-011744-B | <2 |
| WS- 011887 | 2/26/2025 | 2/26/2026 | 4 | Cooler | In hallway across from room E415 | High Left | WF-02262025-011887 | 12/16/2025 | FT-FY26-12082025-011887-A | <2 | FT-FY26-12082025-011887-B | <2 |
| WS- 011888 | 2/26/2025 | 2/26/2026 | 4 | Cooler | In hallway across from room E415 | Low Right | WF-02262025-011888 | 12/16/2025 | FT-FY26-12082025-011888-A | <2 | FT-FY26-12082025-011888-B | <2 |
| WS- 011894 | 8/27/2025 | 8/27/2026 | 4 | Break Room | In break room E406 | | WF-08272025-011894 | 12/16/2025 | FT-FY26-12082025-011894-A | <2 | FT-FY26-12082025-011894-B | <2 |

Food Prep Sink

| Less than 5ppb - Devices requiring no remediation | | | | | | | | | | | |
|---|-----------------------|------------------------|--------------|----------------|---|---------------------|---------------|---------------------------|----------------------------------|---------------------------|----------------------------------|
| Record ID | Filter Installed Date | Filter Expiration Date | Floor | Device Type | Device Location | Water Filter's Name | Date Analyzed | 1st Draw - Sample ID | FT Final Result - 1st Draw (ppb) | 2nd Draw - Sample ID | FT Final Result - 2nd Draw (ppb) |
| WS- 010721 | 12/1/2025 | 12/1/2026 | Ground Floor | Food Prep Sink | In kitchen first clockwise from entry door Left | WF-12012025-010721 | 12/16/2025 | FT-FY26-12082025-010721-A | <2 | FT-FY26-12082025-010721-B | <2 |

Due to changes in water sampling analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.