



Emery Recreation Center Lead in Water Test Results

FY23 Filter Test

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
WS- 005480	12/19/2022	12/19/2023	1	Food Prep Sink	In pantry room 114	WF-12192022-005480	2/13/2023	FT-FY23-01192023-005480-A	<1	FT-FY23-01192023-005480-B	<1	
WS- 005485	3/31/2022	3/31/2023	2	Cooler	In hallway across from elevator	High Left	WF-03312022-005485	2/13/2023	FT-FY23-01192023-005485-A	<1	FT-FY23-01192023-005485-B	<1
WS- 005486	3/31/2022	3/31/2023	2	Cooler	In hallway across from elevator	Low Right	WF-03312022-005486	2/13/2023	FT-FY23-01192023-005486-A	<1	FT-FY23-01192023-005486-B	<1
WS- 005491	3/31/2022	3/31/2023	1	Cooler	In hallway adjacent to gym 115	High Left	WF-03312022-005491	2/13/2023	FT-FY23-01192023-005491-A	<1	FT-FY23-01192023-005491-B	<1
WS- 005492	3/31/2022	3/31/2023	1	Cooler	In hallway adjacent to gym 116	Low Right	WF-03312022-005492	2/13/2023	FT-FY23-01192023-005492-A	<1	FT-FY23-01192023-005492-B	<1
WS- 005550	5/9/2022	5/9/2023	2	Bottle Filler	In gym room 201		WF-05092022-005550	2/13/2023	FT-FY23-01192023-005550-A	<1	FT-FY23-01192023-005550-B	<1
WS- 005551	5/9/2022	5/9/2023	2	Cooler	Hallway next to gym room 201		WF-05092022-005551	2/13/2023	FT-FY23-01192023-005551-A	<1	FT-FY23-01192023-005551-B	<1