



Hart Middle School Lead in Water Test Results

FY21 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 000415	3/16/2021	3/16/2022	1	Health Suite	In health suite	WF-03162021-000415	5/1/2021	FT-FY21-042021-000415-A	<1	FT-FY21-042021-000415-B	<1
WS- 004405	3/16/2021	3/16/2022	3	Break Room	In break room 312	WF-03162021-004405	5/1/2021	FT-FY21-042021-004405-A	<1	FT-FY21-042021-004405-B	<1
WS- 004406	3/16/2021	3/16/2022	3	Cooler	In hallway adjacent to room 321 High Left	WF-03162021-004406	5/1/2021	FT-FY21-042021-004406-A	<1	FT-FY21-042021-004406-B	<1
WS- 004407	3/16/2021	3/16/2022	3	Cooler	In hallway adjacent to room 321 Low Right	WF-03162021-004407	5/1/2021	FT-FY21-042021-004407-A	<1	FT-FY21-042021-004407-B	<1
WS- 004409	3/16/2021	3/16/2022	2	Combo Fountain	In classroom 235 Left	WF-03162021-004409	5/1/2021	FT-FY21-042021-004409-A	<1	FT-FY21-042021-004409-B	<1
WS- 004410	10/6/2020	10/6/2021	2	Combo Faucet	In classroom 235 Right	WF-10062020-004410	5/1/2021	FT-FY21-042021-004410-A	<1	FT-FY21-042021-004410-B	<1
WS- 009120	3/16/2021	3/16/2022	1	Break Room	In break room 101	WF-03162021-009120	5/1/2021	FT-FY21-042021-009120-A	<1	FT-FY21-042021-009120-B	<1
WS- 009912	3/16/2021	3/16/2022	Basement	Cooler	In hallway adjacent to room 023	WF-03162021-009912	5/1/2021	FT-FY21-042021-009912-A	<1	FT-FY21-042021-009912-B	<1
WS- 009920	3/16/2021	3/16/2022	1	Cooler	In hallway adjacent to room 103	WF-03162021-009920	5/1/2021	FT-FY21-042021-009920-A	1.1	FT-FY21-042021-009920-B	<1
WS- 009922	3/16/2021	3/16/2022	1	Combo Fountain	In classroom 117 Right	WF-03162021-009922	5/1/2021	FT-FY21-042021-009922-A	<1	FT-FY21-042021-009922-B	<1
WS- 009923	10/6/2020	10/6/2021	1	Combo Faucet	In classroom 117 Left	WF-10062020-009923	5/1/2021	FT-FY21-042021-009923-A	<1	FT-FY21-042021-009923-B	<1
WS- 009924	10/6/2020	10/6/2021	1	Combo Faucet	In classroom 116 Left	WF-10062020-009924	5/1/2021	FT-FY21-042021-009924-A	<1	FT-FY21-042021-009924-B	<1
WS- 009925	3/16/2021	3/16/2022	1	Combo Fountain	In classroom 116 Right	WF-03162021-009925	5/1/2021	FT-FY21-042021-009925-A	<1	FT-FY21-042021-009925-B	<1
WS- 009926	10/6/2020	10/6/2021	1	Combo Faucet	In classroom 118 Left	WF-10062020-009926	5/1/2021	FT-FY21-042021-009926-A	<1	FT-FY21-042021-009926-B	<1
WS- 009927	3/16/2021	3/16/2022	1	Combo Fountain	In classroom 118 Right	WF-03162021-009927	5/1/2021	FT-FY21-042021-009927-A	<1	FT-FY21-042021-009927-B	<1
WS- 009928	3/16/2021	3/16/2022	1	Combo Fountain	In classroom 119 Right	WF-03162021-009928	5/1/2021	FT-FY21-042021-009928-A	<1	FT-FY21-042021-009928-B	<1
WS- 009929	10/6/2020	10/6/2021	1	Combo Faucet	In classroom 119 Left	WF-10062020-009929	5/1/2021	FT-FY21-042021-009929-A	1.0	FT-FY21-042021-009929-B	<1
WS- 009930	10/6/2020	10/6/2021	1	Combo Faucet	In classroom 114 Left	WF-10062020-009930	5/1/2021	FT-FY21-042021-009930-A	1.4	FT-FY21-042021-009930-B	1.0
WS- 009931	3/16/2021	3/16/2022	1	Combo Fountain	In classroom 114 Right	WF-03162021-009931	5/1/2021	FT-FY21-042021-009931-A	<1	FT-FY21-042021-009931-B	<1
WS- 009932	3/16/2021	3/16/2022	1	Cooler	In girls' locker room	WF-03162021-009932	5/1/2021	FT-FY21-042021-009932-A	<1	FT-FY21-042021-009932-B	<1
WS- 009933	3/16/2021	3/16/2022	1	Cooler	In hallway adjacent to room 119	WF-03162021-009933	5/1/2021	FT-FY21-042021-009933-A	<1	FT-FY21-042021-009933-B	<1
WS- 009936	3/16/2021	3/16/2022	1	Cooler	In hallway adjacent to room 131	WF-03162021-009936	5/1/2021	FT-FY21-042021-009936-A	<1	FT-FY21-042021-009936-B	<1
WS- 009937	3/16/2021	3/16/2022	2	Cooler	In hallway across from room 245 High Left	WF-03162021-009937	5/1/2021	FT-FY21-042021-009937-A	<1	FT-FY21-042021-009937-B	<1
WS- 009938	3/16/2021	3/16/2022	2	Cooler	In hallway across from room 245 Low Right	WF-03162021-009938	5/1/2021	FT-FY21-042021-009938-A	<1	FT-FY21-042021-009938-B	<1
WS- 009939	3/16/2021	3/16/2022	2	Cooler	In hallway adjacent to room 232 High Left	WF-03162021-009939	5/1/2021	FT-FY21-042021-009939-A	<1	FT-FY21-042021-009939-B	<1
WS- 009940	3/16/2021	3/16/2022	2	Cooler	In hallway adjacent to room 232 Low Right	WF-03162021-009940	5/1/2021	FT-FY21-042021-009940-A	<1	FT-FY21-042021-009940-B	<1
WS- 009953	3/16/2021	3/16/2022	2	Break Room	In break room 218	WF-03162021-009953	5/1/2021	FT-FY21-042021-009953-A	<1	FT-FY21-042021-009953-B	<1
WS- 011597	3/16/2021	3/16/2022	1	Cooler	In boys' locker room	WF-03162021-011597	5/1/2021	FT-FY21-042021-011597-A	<1	FT-FY21-042021-011597-B	<1

Food Prep Sink

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 009917	2/16/2021	2/16/2022	Basement	Food Prep Sink	In kitchen first clock wise from entry door Left	WF-02162021-009917	5/1/2021	FT-FY21-042021-009917-A	<1	FT-FY21-042021-009917-B	<1