



Hart MS Lead in Water Test Results

FY26 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 000415	2/18/2025	2/18/2026	1	Health Suite	In health suite	WF-02182025-000415	12/17/2025	FT-FY26-12012025-000415-A	<2	FT-FY26-12012025-000415-B	<2
WS- 004404	2/18/2025	2/18/2026	3	Cooler	In hallway adjacent to room 305	WF-02182025-004404	12/17/2025	FT-FY26-12012025-004404-A	<2	FT-FY26-12012025-004404-B	<2
WS- 004405	2/18/2025	2/18/2026	3	Break Room	In break room 312	WF-02182025-004405	12/17/2025	FT-FY26-12012025-004405-A	<2	FT-FY26-12012025-004405-B	<2
WS- 004406	2/18/2025	2/18/2026	3	Cooler	In hallway adjacent to room 321 High Left	WF-02182025-004406	12/17/2025	FT-FY26-12012025-004406-A	<2	FT-FY26-12012025-004406-B	<2
WS- 004407	2/18/2025	2/18/2026	3	Cooler	In hallway adjacent to room 321 Low Right	WF-02182025-004407	12/17/2025	FT-FY26-12012025-004407-A	<2	FT-FY26-12012025-004407-B	<2
WS- 004409	2/18/2025	2/18/2026	2	Combo Fountain	In classroom 235 Left	WF-02182025-004409	12/17/2025	FT-FY26-12012025-004409-A	<2	FT-FY26-12012025-004409-B	<2
WS- 004541	2/18/2025	2/18/2026	Basement	Bottle Filler	In hallway adjacent to room 023	WF-02182025-004541	12/17/2025	FT-FY26-12012025-004541-A	<2	FT-FY26-12012025-004541-B	<2
WS- 007257	2/18/2025	2/18/2026	1	Bottle Filler	In hallway adjacent to room 123	WF-02182025-007257	12/17/2025	FT-FY26-12012025-007257-A	<2	FT-FY26-12012025-007257-B	<2
WS- 009120	2/18/2025	2/18/2026	1	Break Room	In break room 101	WF-02182025-009120	12/17/2025	FT-FY26-12012025-009120-A	<2	FT-FY26-12012025-009120-B	<2
WS- 009916	2/18/2025	2/18/2026	Basement	Cooler	In cafeteria	WF-02182025-009916	12/17/2025	FT-FY26-12012025-009916-A	<2	FT-FY26-12012025-009916-B	<2
WS- 009920	2/18/2025	2/18/2026	1	Cooler	In hallway adjacent to room 103	WF-02182025-009920	12/17/2025	FT-FY26-12012025-009920-A	<2	FT-FY26-12012025-009920-B	<2
WS- 009922	2/18/2025	2/18/2026	1	Combo Fountain	In classroom 117 Right	WF-02182025-009922	12/17/2025	FT-FY26-12012025-009922-A	<2	FT-FY26-12012025-009922-B	<2
WS- 009923	9/2/2025	9/2/2026	1	Combo Faucet	In classroom 117 Left	WF-09022025-009923	12/17/2025	FT-FY26-12012025-009923-A	<2	FT-FY26-12012025-009923-B	<2
WS- 009924	9/2/2025	9/2/2026	1	Combo Faucet	In classroom 116 Left	WF-09022025-009924	12/17/2025	FT-FY26-12012025-009924-A	<2	FT-FY26-12012025-009924-B	<2
WS- 009925	2/18/2025	2/18/2026	1	Combo Fountain	In classroom 116 Right	WF-02182025-009925	12/17/2025	FT-FY26-12012025-009925-A	<2	FT-FY26-12012025-009925-B	<2
WS- 009928	2/18/2025	2/18/2026	1	Combo Fountain	In classroom 119 Right	WF-02182025-009928	12/17/2025	FT-FY26-12012025-009928-A	<2	FT-FY26-12012025-009928-B	<2
WS- 009929	9/2/2025	9/2/2026	1	Combo Faucet	In classroom 119 Left	WF-09022025-009929	12/17/2025	FT-FY26-12012025-009929-A	<2	FT-FY26-12012025-009929-B	<2
WS- 009930	9/2/2025	9/2/2026	1	Combo Faucet	In classroom 114 Left	WF-09022025-009930	12/17/2025	FT-FY26-12012025-009930-A	<2	FT-FY26-12012025-009930-B	<2
WS- 009931	2/18/2025	2/18/2026	1	Combo Fountain	In classroom 114 Right	WF-02182025-009931	12/17/2025	FT-FY26-12012025-009931-A	<2	FT-FY26-12012025-009931-B	<2
WS- 009934	2/18/2025	2/18/2026	1	Cooler	In hallway adjacent to room 123	WF-02182025-009934	12/17/2025	FT-FY26-12012025-009934-A	<2	FT-FY26-12012025-009934-B	<2
WS- 009935	2/18/2025	2/18/2026	1	Cooler	In hallway adjacent to room 123	WF-02182025-009935	12/17/2025	FT-FY26-12012025-009935-A	<2	FT-FY26-12012025-009935-B	<2
WS- 009936	2/18/2025	2/18/2026	1	Cooler	In hallway adjacent to room 131	WF-02182025-009936	12/17/2025	FT-FY26-12012025-009936-A	<2	FT-FY26-12012025-009936-B	<2
WS- 009938	2/18/2025	2/18/2026	2	Cooler	In hallway across from room 245 Low Right	WF-02182025-009938	12/17/2025	FT-FY26-12012025-009938-A	<2	FT-FY26-12012025-009938-B	<2
WS- 009953	2/18/2025	2/18/2026	2	Break Room	In break room 218	WF-02182025-009953	12/17/2025	FT-FY26-12012025-009953-A	<2	FT-FY26-12012025-009953-B	<2

Food Prep Sink

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 009917	11/25/2025	11/25/2026	Basement	Food Prep Sink	In kitchen first clock wise from entry door Left	WF-11252025-009917	12/17/2025	FT-FY26-12012025-009917-A	<2	FT-FY26-12012025-009917-B	<2

Due to changes in water sampling analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.