



Ketcham Elementary School Lead in Water Test Results



FY21 Filter Test

Less than 5ppb - Devices requiring no remediation

| Record ID | Filter Installed Date | Filter Expiration Date | Floor | Device Type | Device Location | Water Filter's Name | Date Analyzed | 1st Draw - Sample ID | FT Final Result - 1st Draw (ppb) | 2nd Draw - Sample ID | FT Final Result - 2nd Draw (ppb) |
|-----------|-----------------------|------------------------|--------------|----------------|--|---------------------|---------------|-------------------------|----------------------------------|-------------------------|----------------------------------|
| WS-009605 | 3/24/2020 | 3/24/2021 | Ground Floor | Cooler | In hallway adjacent to girls' restroom | WF-03242020-009605 | 2/4/2021 | FT-FY21-012021-009605-A | <1 | FT-FY21-012021-009605-B | <1 |
| WS-009607 | 9/29/2020 | 9/29/2021 | 1 | Combo Faucet | In classroom A-101 | WF-09292020-009607 | 2/4/2021 | FT-FY21-012021-009607-A | <1 | FT-FY21-012021-009607-B | <1 |
| WS-009608 | 3/24/2020 | 3/24/2021 | 1 | Combo Fountain | In classroom A-101 | WF-03242020-009608 | 2/4/2021 | FT-FY21-012021-009608-A | <1 | FT-FY21-012021-009608-B | <1 |
| WS-009610 | 3/24/2020 | 3/24/2021 | 1 | Health Suite | In health suite 105 | WF-03242020-009610 | 2/4/2021 | FT-FY21-012021-009610-A | <1 | FT-FY21-012021-009610-B | <1 |
| WS-009611 | 3/24/2020 | 3/24/2021 | 1 | Cooler | In hallway across from room B-109 | WF-03242020-009611 | 2/4/2021 | FT-FY21-012021-009611-A | <1 | FT-FY21-012021-009611-B | <1 |
| WS-009612 | 3/24/2020 | 3/24/2021 | 1 | Combo Fountain | In classroom B-109 | WF-03242020-009612 | 2/4/2021 | FT-FY21-012021-009612-A | <1 | FT-FY21-012021-009612-B | <1 |
| WS-009613 | 9/29/2020 | 9/29/2021 | 1 | Combo Faucet | In classroom B-109 | WF-09292020-009613 | 2/4/2021 | FT-FY21-012021-009613-A | <1 | FT-FY21-012021-009613-B | <1 |
| WS-009614 | 3/24/2020 | 3/24/2021 | 1 | Combo Fountain | In classroom B-113 | WF-03242020-009614 | 2/4/2021 | FT-FY21-012021-009614-A | <1 | FT-FY21-012021-009614-B | <1 |
| WS-009615 | 9/29/2020 | 9/29/2021 | 1 | Combo Faucet | In classroom B-113 | WF-09292020-009615 | 2/4/2021 | FT-FY21-012021-009615-A | <1 | FT-FY21-012021-009615-B | <1 |
| WS-009616 | 3/24/2020 | 3/24/2021 | 1 | Combo Fountain | In classroom B-114 | WF-03242020-009616 | 2/4/2021 | FT-FY21-012021-009616-A | <1 | FT-FY21-012021-009616-B | <1 |
| WS-009617 | 9/29/2020 | 9/29/2021 | 1 | Combo Faucet | In classroom B-114 | WF-09292020-009617 | 2/4/2021 | FT-FY21-012021-009617-A | <1 | FT-FY21-012021-009617-B | <1 |
| WS-009618 | 3/24/2020 | 3/24/2021 | 1 | Combo Fountain | In classroom B-116 | WF-03242020-009618 | 2/4/2021 | FT-FY21-012021-009618-A | <1 | FT-FY21-012021-009618-B | <1 |
| WS-009619 | 9/29/2020 | 9/29/2021 | 1 | Combo Faucet | In classroom B-116 | WF-09292020-009619 | 2/4/2021 | FT-FY21-012021-009619-A | <1 | FT-FY21-012021-009619-B | <1 |
| WS-009622 | 3/24/2020 | 3/24/2021 | 2 | Break Room | In staff lounge B-202 | WF-03242020-009622 | 2/4/2021 | FT-FY21-012021-009622-A | <1 | FT-FY21-012021-009622-B | <1 |
| WS-009624 | 3/24/2020 | 3/24/2021 | 2 | Cooler | In hallway adjacent restroom | WF-03242020-009624 | 2/4/2021 | FT-FY21-012021-009624-A | <1 | FT-FY21-012021-009624-B | <1 |
| WS-009630 | 3/24/2020 | 3/24/2021 | 2 | Cooler | In hallway adjacent to conference room 204 | WF-03242020-009630 | 2/4/2021 | FT-FY21-012021-009630-A | <1 | FT-FY21-012021-009630-B | <1 |
| WS-009631 | 3/24/2020 | 3/24/2021 | 2 | Cooler | In hallway adjacent to room 205 | WF-03242020-009631 | 2/4/2021 | FT-FY21-012021-009631-A | <1 | FT-FY21-012021-009631-B | <1 |
| WS-009634 | 3/24/2020 | 3/24/2021 | 3 | Break Room | In staff lounge B-302 | WF-03242020-009634 | 2/4/2021 | FT-FY21-012021-009634-A | <1 | FT-FY21-012021-009634-B | <1 |
| WS-009799 | 3/24/2020 | 3/24/2021 | 1 | Break Room | In staff office room B-117 | WF-03242020-009799 | 2/4/2021 | FT-FY21-012021-009799-A | <1 | FT-FY21-012021-009799-B | <1 |
| WS-017023 | 6/29/2020 | 6/29/2021 | Ground Floor | Bottle Filler | In cafeteria | WF-06292020-017023 | 2/4/2021 | FT-FY21-012021-017023-A | <1 | FT-FY21-012021-017023-B | <1 |
| WS-017024 | 6/29/2020 | 6/29/2021 | Ground Floor | Cooler | In cafeteria | WF-06292020-017024 | 2/4/2021 | FT-FY21-012021-017024-A | <1 | FT-FY21-012021-017024-B | <1 |
| WS-017025 | 6/29/2020 | 6/29/2021 | Ground Floor | Cooler | In cafeteria | WF-06292020-017025 | 2/4/2021 | FT-FY21-012021-017025-A | <1 | FT-FY21-012021-017025-B | <1 |

Food Prep Sink

Less than 5ppb - Devices requiring no remediation

| Record ID | Filter Installed Date | Filter Expiration Date | Floor | Device Type | Device Location | Water Filter's Name | Date Analyzed | 1st Draw - Sample ID | FT Final Result - 1st Draw (ppb) | 2nd Draw - Sample ID | FT Final Result - 2nd Draw (ppb) |
|-----------|-----------------------|------------------------|--------------|----------------|--------------------------|---------------------|---------------|-------------------------|----------------------------------|-------------------------|----------------------------------|
| WS-009601 | 1/18/2021 | 1/18/2022 | Ground Floor | Food Prep Sink | In kitchen on east wall | WF-01182021-009601 | 2/4/2021 | FT-FY21-012021-009601-A | <1 | FT-FY21-012021-009601-B | <1 |
| WS-009602 | 1/18/2021 | 1/18/2022 | Ground Floor | Food Prep Sink | In kitchen on north wall | WF-01182021-009602 | 2/4/2021 | FT-FY21-012021-009602-A | <1 | FT-FY21-012021-009602-B | <1 |