



# Ketcham Elementary School Lead in Water Test Results

## FY25 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
WS- 009607	9/3/2024	9/3/2025	1	Combo Faucet	In classroom A-101	WF-09032024-009607	2/7/2025	FT-FY25-12262024-009607-A	<2	FT-FY25-12262024-009607-B	<2	
WS- 009608	2/27/2024	2/27/2025	1	Combo Fountain	In classroom A-101	WF-02272024-009608	2/7/2025	FT-FY25-12262024-009608-A	<2	FT-FY25-12262024-009608-B	<2	
WS- 009610	2/27/2024	2/27/2025	1	Health Suite	In health suite 105	WF-02272024-009610	2/7/2025	FT-FY25-12262024-009610-A	<2	FT-FY25-12262024-009610-B	<2	
WS- 009612	2/27/2024	2/27/2025	1	Combo Fountain	In classroom B-109	WF-02272024-009612	2/7/2025	FT-FY25-12262024-009612-A	<2	FT-FY25-12262024-009612-B	<2	
WS- 009613	9/3/2024	9/3/2025	1	Combo Faucet	In classroom B-109	WF-09032024-009613	2/7/2025	FT-FY25-12262024-009613-A	<2	FT-FY25-12262024-009613-B	<2	
WS- 009614	2/27/2024	2/27/2025	1	Combo Fountain	In classroom B-113	WF-02272024-009614	2/7/2025	FT-FY25-12262024-009614-A	<2	FT-FY25-12262024-009614-B	<2	
WS- 009615	9/3/2024	9/3/2025	1	Combo Faucet	In classroom B-113	WF-09032024-009615	2/7/2025	FT-FY25-12262024-009615-A	<2	FT-FY25-12262024-009615-B	<2	
WS- 009617	9/3/2024	9/3/2025	1	Combo Faucet	In classroom B-114	WF-09032024-009617	2/7/2025	FT-FY25-12262024-009617-A	2.9	FT-FY25-12262024-009617-B	<2	
WS- 009618	2/27/2024	2/27/2025	1	Combo Fountain	In classroom B-116	WF-02272024-009618	2/7/2025	FT-FY25-12262024-009618-A	<2	FT-FY25-12262024-009618-B	<2	
WS- 009619	9/3/2024	9/3/2025	1	Combo Faucet	In classroom B-116	WF-09032024-009619	2/7/2025	FT-FY25-12262024-009619-A	<2	FT-FY25-12262024-009619-B	<2	
WS- 009622	2/27/2024	2/27/2025	2	Break Room	In staff lounge B-202	WF-02272024-009622	2/7/2025	FT-FY25-12262024-009622-A	<2	FT-FY25-12262024-009622-B	<2	
WS- 009636	2/27/2024	2/27/2025	3	Cooler	In hallway adjacent to stairwell 2	WF-02272024-009636	2/7/2025	FT-FY25-12262024-009636-A	<2	FT-FY25-12262024-009636-B	<2	
WS- 009792	2/27/2024	2/27/2025	Ground Floor	Combo Fountain	In classroom B101	WF-02272024-009792	2/7/2025	FT-FY25-12262024-009792-A	<2	FT-FY25-12262024-009792-B	<2	
WS- 009793	2/27/2024	2/27/2025	Ground Floor	Break Room	In break room B109	WF-02272024-009793	2/7/2025	FT-FY25-12262024-009793-A	<2	FT-FY25-12262024-009793-B	<2	
WS- 009794	9/3/2024	9/3/2025	Ground Floor	Combo Faucet	In classroom B104	WF-09032024-009794	2/7/2025	FT-FY25-12262024-009794-A	3.3	FT-FY25-12262024-009794-B	<2	
WS- 009795	2/27/2024	2/27/2025	Ground Floor	Combo Fountain	In classroom B104	WF-02272024-009795	2/7/2025	FT-FY25-12262024-009795-A	<2	FT-FY25-12262024-009795-B	<2	
WS- 009796	9/3/2024	9/3/2025	Ground Floor	Combo Faucet	In classroom B103	WF-09032024-009796	2/7/2025	FT-FY25-12262024-009796-A	<2	FT-FY25-12262024-009796-B	<2	
WS- 009797	2/27/2024	2/27/2025	Ground Floor	Combo Fountain	In classroom B103	WF-02272024-009797	2/7/2025	FT-FY25-12262024-009797-A	<2	FT-FY25-12262024-009797-B	<2	
WS- 009798	9/3/2024	9/3/2025	Ground Floor	Combo Faucet	In classroom B101	WF-09032024-009798	2/7/2025	FT-FY25-12262024-009798-A	<2	FT-FY25-12262024-009798-B	<2	
WS- 009799	2/27/2024	2/27/2025	1	Break Room	In staff office room B-117	WF-02272024-009799	2/7/2025	FT-FY25-12262024-009799-A	<2	FT-FY25-12262024-009799-B	<2	
WS- 009800	2/27/2024	2/27/2025	Ground Floor	Bottle Filler	In hallway adjacent to classroom B104	WF-02272024-009800	2/7/2025	FT-FY25-12262024-009800-A	<2	FT-FY25-12262024-009800-B	<2	
WS- 009801	2/27/2024	2/27/2025	Ground Floor	Cooler	In hallway adjacent to classroom B104	High Right	WF-02272024-009801	2/7/2025	FT-FY25-12262024-009801-A	<2	FT-FY25-12262024-009801-B	<2
WS- 009802	2/27/2024	2/27/2025	Ground Floor	Cooler	In hallway adjacent to classroom B104	Low Left	WF-02272024-009802	2/7/2025	FT-FY25-12262024-009802-A	<2	FT-FY25-12262024-009802-B	<2
WS-017023	12/19/2024	12/19/2025	Ground Floor	Bottle Filler	In cafeteria	WF-12192024-017023	2/7/2025	FT-FY25-12262024-017023-A	<2	FT-FY25-12262024-017023-B	<2	
WS-017024	12/19/2024	12/19/2025	Ground Floor	Cooler	In cafeteria	Low Left	WF-12192024-017024	2/7/2025	FT-FY25-12262024-017024-A	<2	FT-FY25-12262024-017024-B	<2
WS-017025	12/19/2024	12/19/2025	Ground Floor	Cooler	In cafeteria	High Right	WF-12192024-017025	2/7/2025	FT-FY25-12262024-017025-A	<2	FT-FY25-12262024-017025-B	<2

## Food Prep Sink

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
WS- 009601	12/9/2024	12/9/2025	Ground Floor	Food Prep Sink	In kitchen on east wall	WF-12092024-009601	2/7/2025	FT-FY25-12262024-009601-A	<2	FT-FY25-12262024-009601-B	<2	
WS- 009602	12/9/2024	12/9/2025	Ground Floor	Food Prep Sink	In kitchen on north wall	Left	WF-12092024-009602	2/7/2025	FT-FY25-12262024-009602-A	<2	FT-FY25-12262024-009602-B	<2

Due to changes in water sampling analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.