



Malcolm X ES Lead Water Test Results



FY20 Filter Test

| Less than 5ppb - Devices requiring no remediation | | | | | | | | | | | |
|---|-----------------------|------------------------|-------|------------------|---------------------------------|---------------------|---------------|-------------------------|----------------------------------|-------------------------|----------------------------------|
| Record ID | Filter Installed Date | Filter Expiration Date | Floor | Device Type | Device Location | Water Filter's Name | Date Analyzed | 1st Draw - Sample ID | FT Final Result - 1st Draw (ppb) | 2nd Draw - Sample ID | FT Final Result - 2nd Draw (ppb) |
| WS- 009888 | 5/21/2019 | 5/21/2020 | 1 | Cooler | In multi-purpose room | WF-05212019-009888 | 11/4/2019 | FT-FY20-102019-009888-A | <1 | FT-FY20-102019-009888-B | <1 |
| WS- 009889 | 5/21/2019 | 5/21/2020 | 1 | Cooler | In health suite | WF-05212019-009889 | 11/4/2019 | FT-FY20-102019-009889-A | <1 | FT-FY20-102019-009889-B | <1 |
| WS- 009890 | 5/21/2019 | 5/21/2020 | 1 | Break Room | In staff lounge | WF-05212019-009890 | 11/4/2019 | FT-FY20-102019-009890-A | <1 | FT-FY20-102019-009890-B | <1 |
| WS- 009891 | 5/21/2019 | 5/21/2020 | 1 | Cooler | In hallway adjacent to room 109 | WF-05212019-009891 | 11/4/2019 | FT-FY20-102019-009891-A | <1 | FT-FY20-102019-009891-B | <1 |
| WS- 009892 | 10/10/2019 | 10/10/2020 | 1 | Classroom Faucet | In classroom 109 | WF-10102019-009892 | 11/4/2019 | FT-FY20-102019-009892-A | <1 | FT-FY20-102019-009892-B | <1 |
| WS- 009893 | 5/21/2019 | 5/21/2020 | 1 | Cooler | In hallway adjacent to room 115 | WF-05212019-009893 | 11/4/2019 | FT-FY20-102019-009893-A | <1 | FT-FY20-102019-009893-B | <1 |
| WS- 009894 | 5/21/2019 | 5/21/2020 | 1 | Cooler | In hallway across from room 132 | WF-05212019-009894 | 11/4/2019 | FT-FY20-102019-009894-A | <1 | FT-FY20-102019-009894-B | <1 |
| WS- 009895 | 5/21/2019 | 5/21/2020 | 1 | Fountain | In classroom 130 | WF-05212019-009895 | 11/4/2019 | FT-FY20-102019-009895-A | <1 | FT-FY20-102019-009895-B | <1 |
| WS- 009896 | 10/10/2019 | 10/10/2020 | 1 | Classroom Faucet | In classroom 130 | WF-10102019-009896 | 11/4/2019 | FT-FY20-102019-009896-A | <1 | FT-FY20-102019-009896-B | <1 |
| WS- 009897 | 5/21/2019 | 5/21/2020 | 1 | Cooler | In classroom 131 | WF-05212019-009897 | 11/4/2019 | FT-FY20-102019-009897-A | <1 | FT-FY20-102019-009897-B | <1 |
| WS- 009898 | 10/10/2019 | 10/10/2020 | 1 | Classroom Faucet | In classroom 131 | WF-10102019-009898 | 11/4/2019 | FT-FY20-102019-009898-A | <1 | FT-FY20-102019-009898-B | <1 |
| WS- 009900 | 5/21/2019 | 5/21/2020 | 2 | Cooler | In hallway adjacent to room 208 | WF-05212019-009900 | 11/4/2019 | FT-FY20-102019-009900-A | <1 | FT-FY20-102019-009900-B | <1 |
| WS- 009901 | 5/21/2019 | 5/21/2020 | 2 | Cooler | In hallway across from room 202 | WF-05212019-009901 | 11/4/2019 | FT-FY20-102019-009901-A | <1 | FT-FY20-102019-009901-B | <1 |
| WS- 009902 | 5/21/2019 | 5/21/2020 | 2 | Cooler | In hallway adjacent to room 218 | WF-05212019-009902 | 11/4/2019 | FT-FY20-102019-009902-A | <1 | FT-FY20-102019-009902-B | <1 |
| WS- 009904 | 5/21/2019 | 5/21/2020 | 2 | Combo Fountain | In classroom 224 | WF-05212019-009904 | 11/4/2019 | FT-FY20-102019-009904-A | <1 | FT-FY20-102019-009904-B | <1 |
| WS- 009905 | 10/10/2019 | 10/10/2020 | 2 | Combo Faucet | In classroom 225 | WF-10102019-009905 | 11/4/2019 | FT-FY20-102019-009905-A | <1 | FT-FY20-102019-009905-B | <1 |
| WS- 009906 | 5/21/2019 | 5/21/2020 | 2 | Combo Fountain | In classroom 225 | WF-05212019-009906 | 11/4/2019 | FT-FY20-102019-009906-A | <1 | FT-FY20-102019-009906-B | <1 |
| WS- 009907 | 5/21/2019 | 5/21/2020 | 3 | Cooler | In hallway adjacent to room 308 | WF-05212019-009907 | 11/4/2019 | FT-FY20-102019-009907-A | <1 | FT-FY20-102019-009907-B | <1 |
| WS- 009908 | 5/21/2019 | 5/21/2020 | 3 | Cooler | In hallway across from room 303 | WF-05212019-009908 | 11/4/2019 | FT-FY20-102019-009908-A | <1 | FT-FY20-102019-009908-B | <1 |

Food Prep Sink

| Less than 5ppb - Devices requiring no remediation | | | | | | | | | | | |
|---|-----------------------|------------------------|-------|----------------|---|---------------------|---------------|-------------------------|----------------------------------|-------------------------|----------------------------------|
| Record ID | Filter Installed Date | Filter Expiration Date | Floor | Device Type | Device Location | Water Filter's Name | Date Analyzed | 1st Draw - Sample ID | FT Final Result - 1st Draw (ppb) | 2nd Draw - Sample ID | FT Final Result - 2nd Draw (ppb) |
| WS- 009887 | 7/10/2019 | 7/10/2020 | 1 | Food Prep Sink | In kitchen second clockwise from entry door | WF-07102019-009887 | 11/4/2019 | FT-FY20-102019-009887-A | <1 | FT-FY20-102019-009887-B | <1 |

FY20 Filter Test

| Greater than 5ppb - Devices requiring remediation | | | | | | | | | | | |
|---|-----------------------|------------------------|-------|--------------|------------------|---------------------|---------------|-------------------------|----------------------------------|-------------------------|----------------------------------|
| Record ID | Filter Installed Date | Filter Expiration Date | Floor | Device Type | Device Location | Water Filter's Name | Date Analyzed | 1st Draw - Sample ID | FT Final Result - 1st Draw (ppb) | 2nd Draw - Sample ID | FT Final Result - 2nd Draw (ppb) |
| WS- 009903 | 10/10/2019 | 10/10/2020 | 2 | Combo Faucet | In classroom 224 | WF-10102019-009903 | 11/4/2019 | FT-FY20-102019-009903-A | 45 | FT-FY20-102019-009903-B | 1.1 |