



RON BROWN JHS LEAD WATER TEST RESULTS



Initial Filter Test After Installation

Below Actionable Level - Devices Requiring No Remediation

Building Location: Building Name	RECORD ID	Date Analyzed	Floor	Device Type	Device Location	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
RON BROWN JH (FORMERLY ROPER JH)	WS- 003184	8/24/2017	1	Cooler	In hallway across from athletic storage 1241	Low	FT-62017-003184-A	< 1	FT-62017-003184-B	< 1
RON BROWN JH (FORMERLY ROPER JH)	WS- 003185	8/24/2017	1	Bottle Filler	In hallway across from athletic storage 1241 (bottle filler)	High	FT-62017-003185-A	< 1	FT-62017-003185-B	< 1
RON BROWN JH (FORMERLY ROPER JH)	WS- 003186	8/24/2017	1	Cooler	In hallway across from coaches room 1245	Low	FT-62017-003186-A	< 1	FT-62017-003186-B	< 1
RON BROWN JH (FORMERLY ROPER JH)	WS- 003187	8/24/2017	1	Bottle Filler	In hallway across from coaches room 1245 (bottle filler)	High	FT-62017-003187-A	< 1	FT-62017-003187-B	< 1
RON BROWN JH (FORMERLY ROPER JH)	WS- 003188	8/24/2017	1	Cooler	In hallway adjacent to restroom 1181		FT-62017-003188-A	< 1	FT-62017-003188-B	< 1
RON BROWN JH (FORMERLY ROPER JH)	WS- 003189	8/24/2017	1	Bottle Filler	In hallway adjacent to restroom 1181 (bottle filler)	High	FT-62017-003189-A	< 1	FT-62017-003189-B	< 1
RON BROWN JH (FORMERLY ROPER JH)	WS- 003190	8/24/2017	1	Cooler	In hallway adjacent to restroom 1141	Low	FT-62017-003190-A	< 1	FT-62017-003190-B	< 1
RON BROWN JH (FORMERLY ROPER JH)	WS- 003191	8/24/2017	1	Bottle Filler	In hallway adjacent to restroom 1141 (bottle filler)	High	FT-62017-003191-A	< 1	FT-62017-003191-B	< 1
RON BROWN JH (FORMERLY ROPER JH)	WS- 003192	8/24/2017	1	Health Suite	In health suite in treatment room 113		FT-62017-003192-A	< 1	FT-62017-003192-B	< 1
RON BROWN JH (FORMERLY ROPER JH)	WS- 003193	8/24/2017	1	Break Room	In staff lounge 1174		FT-62017-003193-A	< 1	FT-62017-003193-B	< 1
RON BROWN JH (FORMERLY ROPER JH)	WS- 003210	8/24/2017	2	Bottle Filler	In hallway adjacent to room 2131	High	FT-82017-003210-A	< 1	FT-82017-003210-B	< 1
RON BROWN JH (FORMERLY ROPER JH)	WS- 003211	8/24/2017	2	Cooler	In hallway adjacent to room 2131	Low	FT-82017-003211-A	< 1	FT-82017-003211-B	< 1
RON BROWN JH (FORMERLY ROPER JH)	WS- 003212	8/24/2017	2	Bottle Filler	In hallway adjacent to room 2171	High	FT-82017-003212-A	< 1	FT-82017-003212-B	< 1
RON BROWN JH (FORMERLY ROPER JH)	WS- 003213	8/24/2017	2	Cooler	In hallway adjacent to room 2171	Low	FT-82017-003213-A	< 1	FT-82017-003213-B	< 1
RON BROWN JH (FORMERLY ROPER JH)	WS- 003214	8/24/2017	2	Bottle Filler	In hallway adjacent to stairwell B7	High	FT-82017-003214-A	< 1	FT-82017-003214-B	< 1
RON BROWN JH (FORMERLY ROPER JH)	WS- 003215	8/24/2017	2	Cooler	In hallway adjacent to stairwell B7	Low	FT-82017-003215-A	< 1	FT-82017-003215-B	< 1
RON BROWN JH (FORMERLY ROPER JH)	WS- 003216	8/24/2017	2	Bottle Filler	In hallway adjacent to auditorium	High	FT-82017-003216-A	< 1	FT-82017-003216-B	< 1
RON BROWN JH (FORMERLY ROPER JH)	WS- 003217	8/24/2017	2	Cooler	In hallway adjacent to auditorium	Low	FT-82017-003217-A	< 1	FT-82017-003217-B	< 1
RON BROWN JH (FORMERLY ROPER JH)	WS- 003218	8/24/2017	3	Bottle Filler	In hallway adjacent to stairwell A1	High	FT-82017-003218-A	< 1	FT-82017-003218-B	< 1
RON BROWN JH (FORMERLY ROPER JH)	WS- 003219	8/24/2017	3	Cooler	In hallway adjacent to stairwell A1	Low	FT-82017-003219-A	< 1	FT-82017-003219-B	< 1
RON BROWN JH (FORMERLY ROPER JH)	WS- 003220	8/24/2017	3	Bottle Filler	In hallway adjacent to room 3182	High	FT-82017-003220-A	< 1	FT-82017-003220-B	< 1
RON BROWN JH (FORMERLY ROPER JH)	WS- 003221	8/24/2017	3	Cooler	In hallway adjacent to room 3182	Low	FT-82017-003221-A	< 1	FT-82017-003221-B	< 1
RON BROWN JH (FORMERLY ROPER JH)	WS- 003222	8/24/2017	2	Break Room	In staff lounge 2183		FT-82017-003222-A	< 1	FT-82017-003222-B	< 1
RON BROWN JH (FORMERLY ROPER JH)	WS- 003223	8/24/2017	3	Break Room	In staff lounge 3183		FT-82017-003223-A	< 1	FT-82017-003223-B	< 1