



RANDLE HIGHLANDS LEAD WATER TEST RESULTS



Initial Filter Test After Installation

Less than 1 ppb - Device Returned to Service										
	Building Location: Building Name	Water Source ID	Date Analyzed	Floor	Device Type	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	Final Result - 2nd Draw (ppb)
1	RANDLE HIGHLANDS ELEMENTARY SCHOOL	WS- 004178	12/20/2016	2	Break Room	In staff lounge 2207	FT-102016-004178-A	< 1	FT-102016-004178-B	< 1
2	RANDLE HIGHLANDS ELEMENTARY SCHOOL	WS- 004183	12/20/2016	Floor	Classroom Faucet	In classroom 2011	FT-122016-004183-A	< 1	FT-122016-004183-B	< 1
3	RANDLE HIGHLANDS ELEMENTARY SCHOOL	WS- 004186	12/20/2016	Floor	Classroom Faucet	In classroom 2009	FT-122016-004186-A	< 1	FT-122016-004186-B	< 1
4	RANDLE HIGHLANDS ELEMENTARY SCHOOL	WS- 004188	12/20/2016	Floor	Classroom Faucet	In classroom 2006	FT-122016-004188-A	< 1	FT-122016-004188-B	< 1
5	RANDLE HIGHLANDS ELEMENTARY SCHOOL	WS- 004191	12/20/2016	Floor	Classroom Faucet	In classroom 2004	FT-122016-004191-A	< 1	FT-122016-004191-B	< 1
6	RANDLE HIGHLANDS ELEMENTARY SCHOOL	WS- 004192	12/20/2016	Floor	Classroom Faucet	In classroom 2003	FT-122016-004192-A	< 1	FT-122016-004192-B	< 1
7	RANDLE HIGHLANDS ELEMENTARY SCHOOL	WS- 004201	12/20/2016	Basement	Classroom Faucet	In classroom 2B11	FT-122016-004201-A	< 1	FT-122016-004201-B	< 1
8	RANDLE HIGHLANDS ELEMENTARY SCHOOL	WS- 004204	12/20/2016	Basement	Classroom Faucet	In classroom 2B09	FT-122016-004204-A	< 1	FT-122016-004204-B	< 1

Greater than 1 ppb - Devices Shut Off and Corrective Action Taken										
1	RANDLE HIGHLANDS ELEMENTARY SCHOOL	WS- 004195	12/20/2016	Floor	Classroom Faucet	In classroom 2001	FT-122016-004195-A	1.2	FT-122016-004195-B	< 1

First Filter Re-Test (After Filter and Plumbing Check with Aerator Replacement)

Greater than 1 ppb - Devices Remain Shut off, Continued Remediation										
1	RANDLE HIGHLANDS ELEMENTARY SCHOOL	WS- 004195	1/25/2017	Floor	Classroom Faucet	In classroom 2001	FT-122016-004195-A	2.2	FT-122016-004195-B	< 1

Second Filter Re-Test (After Device Replacement)

Less than 1 ppb - Device Returned to Service										
1	RANDLE HIGHLANDS ELEMENTARY SCHOOL	WS- 004195	4/7/2017	Floor	Classroom Faucet	In classroom 2001	FT-122016-004195-A	< 1	FT-122016-004195-B	< 1

Note :

Filter re-tests are only performed to devices that have sampling results greater than 1 ppb