



# Rosedale RC Lead in Water Test Results

## FY25 Filter Test

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 011528	11/26/2024	11/26/2025	1	Food Prep Sink	In kitchen 119	Left	WF-11262024-011528	2/17/2025	FT-FY25-01082025-011528-A	<2	FT-FY25-01082025-011528-B	<2
WS- 011530	2/28/2024	2/28/2025	1	Cooler	In hallway adjacent to office 102	High Left	WF-02282024-011530	2/17/2025	FT-FY25-01082025-011530-A	<2	FT-FY25-01082025-011530-B	<2
WS- 011531	2/28/2024	2/28/2025	1	Cooler	In hallway adjacent to office 102	Low Right	WF-02282024-011531	2/17/2025	FT-FY25-01082025-011531-A	<2	FT-FY25-01082025-011531-B	<2
WS- 011534	11/26/2024	11/26/2025	1	Food Prep Sink	In kitchen 106	Left	WF-11262024-011534	2/17/2025	FT-FY25-01082025-011534-A	<2	FT-FY25-01082025-011534-B	<2
WS- 011536	11/26/2024	11/26/2025	1	Food Prep Sink	In kitchen 106	Right	WF-11262024-011536	2/17/2025	FT-FY25-01082025-011536-A	<2	FT-FY25-01082025-011536-B	<2
WS- 011541	2/28/2024	2/28/2025	1	Cooler	In library		WF-02282024-011541	2/17/2025	FT-FY25-01082025-011541-A	<2	FT-FY25-01082025-011541-B	<2
WS- 011542	2/28/2024	2/28/2025	1	Break Room	In work room in library	Left	WF-02282024-011542	2/17/2025	FT-FY25-01082025-011542-A	<2	FT-FY25-01082025-011542-B	<2

Due to changes in water sampling analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.