



Savoy ES Lead in Water Test Results

FY26 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 008918	9/2/2025	9/2/2026	1	Bottle Filler	In hallway adjacent to multi-purpose room	WF-09022025-008918	11/23/2025	FT-FY26-10172025-008918-A	<2	FT-FY26-10172025-008918-B	<2
WS- 008924	9/2/2025	9/2/2026	1	Cooler	In hallway adjacent to multi-purpose room High Left	WF-09022025-008924	11/23/2025	FT-FY26-10172025-008924-A	<2	FT-FY26-10172025-008924-B	<2
WS- 008925	9/2/2025	9/2/2026	1	Cooler	In hallway adjacent to multi-purpose room Low Right	WF-09022025-008925	11/23/2025	FT-FY26-10172025-008925-A	<2	FT-FY26-10172025-008925-B	<2
WS- 008926	4/22/2025	4/22/2026	1	Cooler	In hallway adjacent to room 125 High Left	WF-04222025-008926	11/23/2025	FT-FY26-10172025-008926-A	<2	FT-FY26-10172025-008926-B	<2
WS- 008928	4/22/2025	4/22/2026	1	Cooler	In hallway across from room 107 High Left	WF-04222025-008928	11/23/2025	FT-FY26-10172025-008928-A	<2	FT-FY26-10172025-008928-B	<2
WS- 008929	4/22/2025	4/22/2026	1	Cooler	In hallway across from room 107 Low Right	WF-04222025-008929	11/23/2025	FT-FY26-10172025-008929-A	<2	FT-FY26-10172025-008929-B	<2
WS- 008930	8/5/2025	8/5/2026	1	Combo Faucet	In classroom 109 Left	WF-08052025-008930	11/23/2025	FT-FY26-10172025-008930-A	2.1	FT-FY26-10172025-008930-B	<2
WS- 008931	4/22/2025	4/22/2026	1	Combo Fountain	In classroom 109 Right	WF-04222025-008931	11/23/2025	FT-FY26-10172025-008931-A	<2	FT-FY26-10172025-008931-B	<2
WS- 008932	8/5/2025	8/5/2026	1	Combo Faucet	In classroom 111 Left	WF-08052025-008932	11/23/2025	FT-FY26-10172025-008932-A	<2	FT-FY26-10172025-008932-B	<2
WS- 008933	4/22/2025	4/22/2026	1	Combo Fountain	In classroom 111 Right	WF-04222025-008933	11/23/2025	FT-FY26-10172025-008933-A	<2	FT-FY26-10172025-008933-B	<2
WS- 008934	8/5/2025	8/5/2026	1	Combo Faucet	In classroom 113 Left	WF-08052025-008934	11/23/2025	FT-FY26-10172025-008934-A	<2	FT-FY26-10172025-008934-B	<2
WS- 008935	4/22/2025	4/22/2026	1	Combo Fountain	In classroom 113 Right	WF-04222025-008935	11/23/2025	FT-FY26-10172025-008935-A	<2	FT-FY26-10172025-008935-B	<2
WS- 008936	8/5/2025	8/5/2026	1	Combo Faucet	In classroom 115 Left	WF-08052025-008936	11/23/2025	FT-FY26-10172025-008936-A	<2	FT-FY26-10172025-008936-B	<2
WS- 008937	4/22/2025	4/22/2026	1	Combo Fountain	In classroom 115 Right	WF-04222025-008937	11/23/2025	FT-FY26-10172025-008937-A	<2	FT-FY26-10172025-008937-B	<2
WS- 008938	8/5/2025	8/5/2026	1	Combo Faucet	In classroom 120 Left	WF-08052025-008938	11/23/2025	FT-FY26-10172025-008938-A	<2	FT-FY26-10172025-008938-B	<2
WS- 008939	4/22/2025	4/22/2026	1	Combo Fountain	In classroom 120 Right	WF-04222025-008939	11/23/2025	FT-FY26-10172025-008939-A	<2	FT-FY26-10172025-008939-B	<2
WS- 008940	8/5/2025	8/5/2026	1	Combo Faucet	In classroom 122 Left	WF-08052025-008940	11/23/2025	FT-FY26-10172025-008940-A	<2	FT-FY26-10172025-008940-B	<2
WS- 008941	4/22/2025	4/22/2026	1	Combo Fountain	In classroom 122 Right	WF-04222025-008941	11/23/2025	FT-FY26-10172025-008941-A	<2	FT-FY26-10172025-008941-B	<2
WS- 008942	4/22/2025	4/22/2026	1	Health Suite	In health suite 108	WF-04222025-008942	11/23/2025	FT-FY26-10172025-008942-A	<2	FT-FY26-10172025-008942-B	<2
WS- 008946	4/22/2025	4/22/2026	2	Break Room	In staff lounge 203	WF-04222025-008946	11/23/2025	FT-FY26-10172025-008946-A	<2	FT-FY26-10172025-008946-B	<2
WS- 008957	4/22/2025	4/22/2026	2	Cooler	In hallway adjacent to room 208 High Left	WF-04222025-008957	11/23/2025	FT-FY26-10172025-008957-A	<2	FT-FY26-10172025-008957-B	<2
WS- 008958	4/22/2025	4/22/2026	2	Cooler	In hallway adjacent to room 208 Low Right	WF-04222025-008958	11/23/2025	FT-FY26-10172025-008958-A	<2	FT-FY26-10172025-008958-B	<2
WS- 008963	4/22/2025	4/22/2026	2	Cooler	In media center room 215 High Left	WF-04222025-008963	11/23/2025	FT-FY26-10172025-008963-A	<2	FT-FY26-10172025-008963-B	<2
WS- 008964	4/22/2025	4/22/2026	2	Cooler	In media center room 215 Low Right	WF-04222025-008964	11/23/2025	FT-FY26-10172025-008964-A	<2	FT-FY26-10172025-008964-B	<2
WS- 008965	4/22/2025	4/22/2026	3	Cooler	In hallway across from room 300 High Left	WF-04222025-008965	11/23/2025	FT-FY26-10172025-008965-A	<2	FT-FY26-10172025-008965-B	<2
WS- 008966	4/22/2025	4/22/2026	3	Cooler	In hallway across from room 300 Low Right	WF-04222025-008966	11/23/2025	FT-FY26-10172025-008966-A	<2	FT-FY26-10172025-008966-B	<2
WS- 008971	4/22/2025	4/22/2026	3	Cooler	In hallway adjacent to room 306 High Left	WF-04222025-008971	11/23/2025	FT-FY26-10172025-008971-A	<2	FT-FY26-10172025-008971-B	<2
WS- 008972	4/22/2025	4/22/2026	3	Cooler	In hallway adjacent to room 306 Low Right	WF-04222025-008972	11/23/2025	FT-FY26-10172025-008972-A	<2	FT-FY26-10172025-008972-B	<2
WS- 012562	4/22/2025	4/22/2026	1	Break Room	In main office adjacent to room 110	WF-04222025-012562	11/23/2025	FT-FY26-10172025-012562-A	<2	FT-FY26-10172025-012562-B	<2

Food Prep Sink

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 008920	12/9/2024	12/9/2025	1	Food Prep Sink	In kitchen first clockwise from entry door	Left	WF-12092024-008920	11/23/2025	FT-FY26-10172025-008920-A	<2	FT-FY26-10172025-008920-B	<2
WS- 008921	12/9/2024	12/9/2025	1	Food Prep Sink	In kitchen second clockwise from entry door	Mid	WF-12092024-008921	11/23/2025	FT-FY26-10172025-008921-A	<2	FT-FY26-10172025-008921-B	<2
WS- 008923	12/9/2024	12/9/2025	1	Food Prep Sink	In kitchen fourth clockwise from entry door		WF-12092024-008923	11/23/2025	FT-FY26-10172025-008923-A	<2	FT-FY26-10172025-008923-B	<2

Due to changes in water sampling analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.