



SEATON ES LEAD WATER TEST RESULTS



Initial Filter Test After Installation

Less than 1 ppb - Device Returned to Service										
	Building Location: Building Name	Water Source ID	Date Analyzed	Floor	Device Type	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	Final Result - 2nd Draw (ppb)
1	SEATON ELEMENTARY SCHOOL	WS- 002503	1/11/2017	1	Combo Faucet	In classroom 109 Left	FT-122016-002503-A	< 1	FT-122016-002503-B	< 1
2	SEATON ELEMENTARY SCHOOL	WS- 002514	1/11/2017	1	Combo Faucet	In classroom 122 Left	FT-122016-002514-A	< 1	FT-122016-002514-B	< 1
3	SEATON ELEMENTARY SCHOOL	WS- 002518	1/11/2017	1	Combo Faucet	In classroom 124 Left	FT-122016-002518-A	< 1	FT-122016-002518-B	< 1
4	SEATON ELEMENTARY SCHOOL	WS- 002520	1/11/2017	1	Combo Faucet	In classroom 127 Left	FT-122016-002520-A	< 1	FT-122016-002520-B	< 1
5	SEATON ELEMENTARY SCHOOL	WS- 002525	1/11/2017	2	Classroom Faucet	In classroom 210 Left	FT-122016-002525-A	< 1	FT-122016-002525-B	< 1

Greater than 1 ppb - Devices Shut Off and Corrective Action Taken										
1	SEATON ELEMENTARY SCHOOL	WS- 002505	1/11/2017	1	Combo Faucet	In classroom 111 Left	FT-122016-002505-A	2.3	FT-122016-002505-B	< 1
2	SEATON ELEMENTARY SCHOOL	WS- 002507	1/11/2017	1	Combo Faucet	In health suite Left	FT-122016-002507-A	8.4	FT-122016-002507-B	< 1
3	SEATON ELEMENTARY SCHOOL	WS- 002508	1/11/2017	1	Classroom Faucet	In classroom 113	FT-122016-002508-A	3.1	FT-122016-002508-B	< 1
4	SEATON ELEMENTARY SCHOOL	WS- 002516	1/11/2017	1	Combo Faucet	In classroom 125 Left	FT-122016-002516-A	1.7	FT-122016-002516-B	< 1
5	SEATON ELEMENTARY SCHOOL	WS- 002524	1/11/2017	2	Break Room	In staff lounge 204	FT-112016-002524-A	4.8	FT-112016-002524-B	< 1
6	SEATON ELEMENTARY SCHOOL	WS- 002529	1/11/2017	3	Combo Faucet	In classroom 307 Left	FT-122016-002529-A	1.4	FT-122016-002529-B	< 1
7	SEATON ELEMENTARY SCHOOL	WS- 002531	1/11/2017	3	Combo Faucet	In classroom 309 Left	FT-122016-002531-A	5.9	FT-122016-002531-B	< 1

First Filter Re-Test (After Filter and Plumbing Check with Aerator Replacement)

Less than 1 ppb - Device Returned to Service										
1	SEATON ELEMENTARY SCHOOL	WS- 002507	2/8/2017	1	Combo Faucet	In health suite Left	FT-122016-002507-A	< 1	FT-122016-002507-B	< 1
2	SEATON ELEMENTARY SCHOOL	WS- 002516	2/8/2017	1	Combo Faucet	In classroom 125 Left	FT-122016-002516-A	< 1	FT-122016-002516-B	< 1
3	SEATON ELEMENTARY SCHOOL	WS- 002524	2/8/2017	2	Break Room	In staff lounge 204	FT-112016-002524-A	< 1	FT-112016-002524-B	< 1
4	SEATON ELEMENTARY SCHOOL	WS- 002529	2/8/2017	3	Combo Faucet	In classroom 307 Left	FT-122016-002529-A	< 1	FT-122016-002529-B	< 1

Greater than 1 ppb - Devices Remain Shut off, Continued Remediation										
1	SEATON ELEMENTARY SCHOOL	WS- 002505	2/8/2017	1	Combo Faucet	In classroom 111 Left	FT-122016-002505-A	1.6	FT-122016-002505-B	< 1
2	SEATON ELEMENTARY SCHOOL	WS- 002508	2/8/2017	1	Classroom Faucet	In classroom 113	FT-122016-002508-A	4.1	FT-122016-002508-B	< 1
3	SEATON ELEMENTARY SCHOOL	WS- 002531	2/8/2017	3	Combo Faucet	In classroom 309 Left	FT-122016-002531-A	5.8	FT-122016-002531-B	< 1

Second Filter Re-Test (After Device Replacement)

Greater than 1 ppb - Devices Remain Shut off, Continued Remediation										
1	SEATON ELEMENTARY SCHOOL	WS- 002505	3/14/2017	1	Combo Faucet	In classroom 111 Left	FT-122016-002505-A	2.3	FT-122016-002505-B	< 1
2	SEATON ELEMENTARY SCHOOL	WS- 002508	3/14/2017	1	Classroom Faucet	In classroom 113	FT-122016-002508-A	2.9	FT-122016-002508-B	< 1
3	SEATON ELEMENTARY SCHOOL	WS- 002531	3/14/2017	3	Combo Faucet	In classroom 309 Left	FT-122016-002531-A	3.8	FT-122016-002531-B	< 1

Filter Re-Test (h # After Dual Supply Faucet Installation)

Less than 5 ppb - Devices Returned to Service											
1	SEATON ELEMENTARY SCHOOL	WS- 002505	8/11/2017	1	Combo Faucet	In classroom 111	Left	FT-122016-002505-A	< 1	FT-122016-002505-B	< 1
2	SEATON ELEMENTARY SCHOOL	WS- 002508	8/11/2017	1	Classroom Faucet	In classroom 113		FT-122016-002508-A	< 1	FT-122016-002508-B	< 1
3	SEATON ELEMENTARY SCHOOL	WS- 002531	8/11/2017	3	Combo Faucet	In classroom 309	Left	FT-122016-002531-A	< 1	FT-122016-002531-B	< 1