



# Turkey Thicket RC Lead in Water Test Results



## FY20 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 005503	4/11/2019	4/11/2020	1	Cooler	In pool area across from men's locker room High	WF-04112019-005503	2/26/2020	FT-FY20-012020-005503-A	<1	FT-FY20-012020-005503-B	<1
WS- 005504	4/11/2019	4/11/2020	1	Cooler	In pool area across from men's locker room Low	WF-04112019-005504	2/26/2020	FT-FY20-012020-005504-A	<1	FT-FY20-012020-005504-B	<1
WS- 005505	4/11/2019	4/11/2020	1	Food Prep Sink	In kitchen 104	WF-04112019-005505	2/26/2020	FT-FY20-012020-005505-A	<1	FT-FY20-012020-005505-B	<1
WS- 005506	4/11/2019	4/11/2020	1	Food Prep Sink	In multi-purpose room 102	WF-04112019-005506	2/26/2020	FT-FY20-012020-005506-A	<1	FT-FY20-012020-005506-B	<1
WS- 005507	4/11/2019	4/11/2020	1	Cooler	In lobby adjacent to weights and exercise room 118 High	WF-04112019-005507	2/26/2020	FT-FY20-012020-005507-A	<1	FT-FY20-012020-005507-B	<1
WS- 005508	4/11/2019	4/11/2020	1	Cooler	In lobby adjacent to weights and exercise room 119 Low	WF-04112019-005508	2/26/2020	FT-FY20-012020-005508-A	<1	FT-FY20-012020-005508-B	<1