



Turkey Thicket Recreation Center Lead in Water Test Results

FY23 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 005503	5/16/2022	5/16/2023	1	Cooler	In pool area across from men's locker room High	WF-05162022-005503	2/21/2023	FT-FY23-02022023-005503-A	<1	FT-FY23-02022023-005503-B	<1
WS- 005504	5/16/2022	5/16/2023	1	Cooler	In pool area across from men's locker room Low	WF-05162022-005504	2/21/2023	FT-FY23-02022023-005504-A	<1	FT-FY23-02022023-005504-B	<1
WS- 005505	1/4/2023	1/4/2024	1	Food Prep Sink	In kitchen 104	WF-01042023-005505	2/21/2023	FT-FY23-02022023-005505-A	<1	FT-FY23-02022023-005505-B	<1
WS- 005506	1/4/2023	1/4/2024	1	Food Prep Sink	In multi-purpose room 102	WF-01042023-005506	2/21/2023	FT-FY23-02022023-005506-A	<1	FT-FY23-02022023-005506-B	1.3
WS- 005507	5/16/2022	5/16/2023	1	Cooler	In lobby adjacent to weights and exercise room 118 High	WF-05162022-005507	2/21/2023	FT-FY23-02022023-005507-A	<1	FT-FY23-02022023-005507-B	<1
WS- 005508	5/16/2022	5/16/2023	1	Cooler	In lobby adjacent to weights and exercise room 119 Low	WF-05162022-005508	2/21/2023	FT-FY23-02022023-005508-A	<1	FT-FY23-02022023-005508-B	<1