

Turkey Thicket Recreation Center Lead in Water Test Results

FY24 Filter Test

| Less than 5ppb - Devices requiring no remediation | | | | | | | | | | | |
|---|-----------------------------|------------------------------|-------|----------------|---|---------------------|------------------|---------------------------|--|---------------------------|--|
| Record ID | Filter Installed Date | Filter Expiration Date | Floor | Device Type | Device Location | Water Filter's Name | Date Analyzed | 1st Draw - Sample ID | FT Final Result - 1st Draw (ppb) | 2nd Draw - Sample ID | FT Final Result - 2nd Draw (ppb) |
| WS- 005503 | 4/19/2024 | 4/19/2025 | 1 | Cooler | In pool area across from men's locker room High | WF-04192024-005503 | 5/10/2024 | FT-FY24-04242024-005503-A | <1 | FT-FY24-04242024-005503-B | <1 |
| WS- 005505 | 11/29/2023 | 11/29/2024 | 1 | Food Prep Sink | In kitchen 104 | WF-11292023-005505 | 5/10/2024 | FT-FY24-04242024-005505-A | <1 | FT-FY24-04242024-005505-B | <1 |
| WS- 005506 | 11/29/2023 | 11/29/2024 | 1 | Food Prep Sink | In multi-purpose room 102 | WF-11292023-005506 | 5/10/2024 | FT-FY24-04242024-005506-A | <1 | FT-FY24-04242024-005506-B | <1 |
| WS- 005507 | 4/19/2024 | 4/19/2025 | 1 | Cooler | In lobby adjacent to weights and exercise room 118 High | WF-04192024-005507 | 5/10/2024 | FT-FY24-04242024-005507-A | <1 | FT-FY24-04242024-005507-B | <1 |
| WS- 005508 | 4/19/2024 | 4/19/2025 | 1 | Cooler | In lobby adjacent to weights and exercise room 119 Low | WF-04192024-005508 | 5/10/2024 | FT-FY24-04242024-005508-A | <1 | FT-FY24-04242024-005508-B | <1 |