



Woody Ward Recreation Center Lead in Water Test Results

FY23 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 001570	6/8/2023	6/8/2024	1	Cooler	In hallway adjacent to room 111 admin office	WF-06082023-001570	6/20/2023	FT-FY23-06122023-001570-A	<1	FT-FY23-06122023-001570-B	<1
WS- 001571	6/8/2023	6/8/2024	1	Cooler	In hallway across for 109 weight room	WF-06082023-001571	6/20/2023	FT-FY23-06122023-001571-A	<1	FT-FY23-06122023-001571-B	<1
WS- 001572	6/8/2023	6/8/2024	1	Food Prep Sink	In kitchen 106	WF-06082023-001572	6/20/2023	FT-FY23-06122023-001572-A	<1	FT-FY23-06122023-001572-B	<1
WS- 001578	6/8/2023	6/8/2024	1	Combo Fountain	In room 103 arts and crafts	WF-06082023-001578	6/20/2023	FT-FY23-06122023-001578-A	<1	FT-FY23-06122023-001578-B	<1
WS- 001579	6/8/2023	6/8/2024	Basement	Cooler	In hallway adjacent to 012B men's locker room High Left	WF-06082023-001579	6/20/2023	FT-FY23-06122023-001579-A	<1	FT-FY23-06122023-001579-B	<1
WS- 001581	6/8/2023	6/8/2024	Basement	Cooler	In hallway adjacent to 012B men's locker room Low Right	WF-06082023-001581	6/20/2023	FT-FY23-06122023-001581-A	<1	FT-FY23-06122023-001581-B	<1