



## Woody Ward Recreation Center Lead in Water Test Results

### FY24 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 001570	4/24/2024	4/24/2025	1	Cooler	In hallway adjacent to room 111 admin office	WF-04242024-001570	5/7/2024	FT-FY24-04242024-001570-A	<1	FT-FY24-04242024-001570-B	<1
WS- 001571	4/24/2024	4/24/2025	1	Cooler	In hallway across for 109 weight room	WF-04242024-001571	5/7/2024	FT-FY24-04242024-001571-A	<1	FT-FY24-04242024-001571-B	<1
WS- 001572	12/27/2023	12/27/2024	1	Food Prep Sink	In kitchen 106	WF-12272023-001572	5/7/2024	FT-FY24-04242024-001572-A	2.0	FT-FY24-04242024-001572-B	<1
WS- 001578	4/24/2024	4/24/2025	1	Combo Fountain	In room 103 arts and crafts	WF-04242024-001578	5/7/2024	FT-FY24-04242024-001578-A	<1	FT-FY24-04242024-001578-B	<1
WS- 001579	4/24/2024	4/24/2025	Basement	Cooler	In hallway adjacent to 012B men's locker room High Left	WF-04242024-001579	5/7/2024	FT-FY24-04242024-001579-A	<1	FT-FY24-04242024-001579-B	<1
WS- 001581	4/24/2024	4/24/2025	Basement	Cooler	In hallway adjacent to 012B men's locker room Low Right	WF-04242024-001581	5/7/2024	FT-FY24-04242024-001581-A	<1	FT-FY24-04242024-001581-B	<1