



BALD EAGLE REC LEAD WATER TEST RESULTS

May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1 BALD EAGLE	5/19/2016	WS-012587	Cooler	Ground Floor	In upper cooler north wall in corridor across from men's and women's room Left High	WT-042916-12604-A	< 2	WT-042916-12604-B	< 2				
2 BALD EAGLE	5/19/2016	WS-012588	Cooler	Ground Floor	In upper cooler north wall in corridor across from men's and women's room Right Low	WT-042916-12605-A	< 2	WT-042916-12605-B	< 2				
3 BALD EAGLE	5/19/2016	WS-012589	Cooler	Ground Floor	In corridor across from fitness room 212 Low	WT-042916-12606-A	< 2	WT-042916-12606-B	< 2				
4 BALD EAGLE	5/19/2016	WS-012590	Cooler	Ground Floor	In corridor across from fitness room 212 High	WT-042916-12607-A	< 2	WT-042916-12607-B	< 2				
5 BALD EAGLE	5/19/2016	WS-012591	Other	Ground Floor	In kitchen room 101 north wall sink	WT-042916-12608-A	< 2	WT-042916-12608-B	< 2				
6 BALD EAGLE	5/19/2016	WS-012592	Other	Ground Floor	In kitchen room 101 north wall (spray nozzle)	WT-042916-12609-A	< 2	WT-042916-12609-B	< 2				
7 BALD EAGLE	5/19/2016	WS-012593	Other	Ground Floor	In pantry room 213 north wall sink faucet	WT-042916-12610-A	8.2	WT-042916-12610-B	< 2				
8 BALD EAGLE	5/19/2016	WS-012594	Other	Ground Floor	In pantry room 213 north wall (spray nozzle)	WT-042916-12611-A	5.4	WT-042916-12611-B	< 2				
9 BALD EAGLE	5/19/2016	WS-012595	Cooler	Ground Floor	In Boxing annex east wall Right Low	WT-042916-12612-A	< 2	WT-042916-12612-B	< 2				
10 BALD EAGLE	5/19/2016	WS-012596	Cooler	Ground Floor	In Boxing annex east wall Left High	WT-042916-12613-A	< 2	WT-042916-12613-B	< 2				
11 BALD EAGLE	5/19/2016	WS-012597	Other	Ground Floor	In Boxing annex pantry room 110 south wall sink faucet	WT-042916-12614-A	< 2	WT-042916-12614-B	< 2				
12 BALD EAGLE	5/19/2016	WS-012598	Other	Ground Floor	In Boxing annex pantry room 110 south wall spray nossle	WT-042916-12615-A	2.7	WT-042916-12615-B	< 2				
13 BALD EAGLE	5/19/2016	WS-012599	Classroom	Ground Floor	In class room 120 east wall	WT-042916-12616-A	3.9	WT-042916-12616-B	3.1				
14 BALD EAGLE	5/19/2016	WS-012600	Other	Ground Floor	In boiler room south wall (water source)	WT-042916-12617-A	6.7	WT-042916-12617-B	< 2				

Footnotes:

- A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.
- B - Second draw sample is collected after a 60 second flush at that device after the first draw.