



# EAST POTOMAC PARK LEAD WATER TEST RESULTS May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1 EAST POTOMAC PARK POOL & BATHHOUSE	5/24/2016	WS- 006380	Other	Basement	In boiler room east wall (water source)	WT-042916-6397- A	< 1	WT-042916-6397- B	< 1				
2 EAST POTOMAC PARK POOL & BATHHOUSE	5/24/2016	WS- 006381	Cooler	Ground Floor	Exterior adjacent to pool and women's locker room Left	WT-042916-6398- A	1.6	WT-042916-6398- B	1.4				
3 EAST POTOMAC PARK POOL & BATHHOUSE	5/24/2016	WS- 006382	Cooler	Ground Floor	Exterior, adjacent to pool and men's locker room Right	WT-042916-6399- A	15.4	WT-042916-6399- B	15	Filtered	7/1/2016	<1	<1
4 EAST POTOMAC PARK POOL & BATHHOUSE	5/24/2016	WS- 006383	Other	Ground Floor	In men's locker room north wall (sink)	WT-042916-6400- A	< 1	WT-042916-6400- B	< 1				
5 EAST POTOMAC PARK POOL & BATHHOUSE	5/24/2016	WS- 006384	Other	Ground Floor	In men's locker room west wall (sink)	WT-042916-6401- A	3.3	WT-042916-6401- B	< 1				
6 EAST POTOMAC PARK POOL & BATHHOUSE	5/24/2016	WS- 006385	Other	Ground Floor	In women's locker room west wall (sink)	WT-042916-6402- A	1.2	WT-042916-6402- B	< 1				
7 EAST POTOMAC PARK POOL & BATHHOUSE	5/24/2016	WS- 006386	Other	Ground Floor	In women's locker room south wall sink Right	WT-042916-6403- A	4.7	WT-042916-6403- B	< 1				
8 EAST POTOMAC PARK POOL & BATHHOUSE	5/24/2016	WS- 006387	Other	Ground Floor	In women's locker room south wall sink Left	WT-042916-6404- A	2.9	WT-042916-6404- B	< 1				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.