



# ELIOT-HINE LEAD WATER TEST RESULTS

May 24th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1	ELIOT-HINE MIDDLE SCHOOL	5/13/2016	WS- 009668	Utility	Basement	In boiler room	WT-042916-9685- A	1.9	WT-042916-9685- B	3.7			
2	ELIOT-HINE MIDDLE SCHOOL	5/13/2016	WS- 009669	Cooler	Basement	In basement in cafeteria	WT-042916-9686- A	< 1	WT-042916-9686- B	< 1			
3	ELIOT-HINE MIDDLE SCHOOL	5/13/2016	WS- 009670	Cooler	Basement	In basement in teacher's dining room B-26	WT-042916-9687- A	< 1	WT-042916-9687- B	< 1			
4	ELIOT-HINE MIDDLE SCHOOL	5/13/2016	WS- 009671	Kitchen	Basement	In basement in kitchen adjacent to restroom	WT-042916-9688- A	< 1	WT-042916-9688- B	< 1			
5	ELIOT-HINE MIDDLE SCHOOL	5/13/2016	WS- 009672	Kitchen	Basement	In basement in kitchen across restroom Left	WT-042916-9689- A	< 1	WT-042916-9689- B	< 1			
6	ELIOT-HINE MIDDLE SCHOOL	5/13/2016	WS- 009673	Kitchen	Basement	In basement in kitchen across restroom Right	WT-042916-9690- A	< 1	WT-042916-9690- B	< 1			
7	ELIOT-HINE MIDDLE SCHOOL	5/13/2016	WS- 009674	Cooler	Basement	In basement adjacent to storage room B-48	WT-042916-9691- A	< 1	WT-042916-9691- B	< 1			
8	ELIOT-HINE MIDDLE SCHOOL	5/13/2016	WS- 009675	Cooler	Basement	In basement in multi-use room	WT-042916-9692- A	< 1	WT-042916-9692- B	< 1			
9	ELIOT-HINE MIDDLE SCHOOL	5/13/2016	WS- 009676	Cooler	1	In first floor hallway adjacent to office 1-152	WT-042916-9693- A	< 1	WT-042916-9693- B	< 1			
10	ELIOT-HINE MIDDLE SCHOOL	5/13/2016	WS- 009677	Cooler	1	In first floor hallway adjacent to classroom 1-166	WT-042916-9694- A	< 1	WT-042916-9694- B	< 1			
11	ELIOT-HINE MIDDLE SCHOOL	5/13/2016	WS- 009678	Cooler	1	In first floor hallway across to classroom 1-077	WT-042916-9695- A	< 1	WT-042916-9695- B	< 1			
12	ELIOT-HINE MIDDLE SCHOOL	5/13/2016	WS- 009679	Cooler	1	In first floor hallway adjacent to classroom 1-070	WT-042916-9696- A	< 1	WT-042916-9696- B	< 1			
13	ELIOT-HINE MIDDLE SCHOOL	5/13/2016	WS- 009680	Health Suite	1	In health suite in bathroom	WT-042916-9697- A	< 1	WT-042916-9697- B	< 1			
14	ELIOT-HINE MIDDLE SCHOOL	5/13/2016	WS- 009681	Cooler	1	In first floor hallway across from principal's office 1-099	WT-042916-9698- A	< 1	WT-042916-9698- B	< 1			
15	ELIOT-HINE MIDDLE SCHOOL	5/13/2016	WS- 009682	Cooler	2	In second floor hallway adjacent to computer lab 2-198	WT-042916-9699- A	< 1	WT-042916-9699- B	< 1			
16	ELIOT-HINE MIDDLE SCHOOL	5/13/2016	WS- 009683	Cooler	2	In second floor hallway adjacent to classroom 2-206	WT-042916-9700- A	< 1	WT-042916-9700- B	< 1			
17	ELIOT-HINE MIDDLE SCHOOL	5/13/2016	WS- 009684	Cooler	2	In second floor hallway adjacent to classroom 2-210	WT-042916-9701- A	< 1	WT-042916-9701- B	< 1			
18	ELIOT-HINE MIDDLE SCHOOL	5/13/2016	WS- 009685	Cooler	2	In second floor hallway adjacent to classroom 2-224	WT-042916-9702- A	< 1	WT-042916-9702- B	< 1			
19	ELIOT-HINE MIDDLE SCHOOL	5/13/2016	WS- 009686	Cooler	3	In third floor hallway adjacent to classroom 3-266	WT-042916-9703- A	< 1	WT-042916-9703- B	< 1			
20	ELIOT-HINE MIDDLE SCHOOL	5/13/2016	WS- 009687	Cooler	3	In third floor hallway adjacent to classroom 3-262	WT-042916-9704- A	< 1	WT-042916-9704- B	< 1			
21	ELIOT-HINE MIDDLE SCHOOL	5/13/2016	WS- 009688	Cooler	3	In third floor hallway adjacent to staff resource room 3-255	WT-042916-9705- A	< 1	WT-042916-9705- B	< 1			
22	ELIOT-HINE MIDDLE SCHOOL	5/13/2016	WS- 009689	Cooler	3	In third floor hallway adjacent to classroom 3-277	WT-042916-9706- A	< 1	WT-042916-9706- B	< 1			
23	ELIOT-HINE MIDDLE SCHOOL	5/13/2016	WS- 009690	Cooler	Basement	In cafeteria adjacent to boiler room stairs	WT-042916-9707- A	< 1	WT-042916-9707- B	< 1			
24	ELIOT-HINE MIDDLE SCHOOL	5/13/2016	WS- 009691	Cooler	2	In second floor hallway adjacent to room 2-171	WT-042916-9708- A	< 1	WT-042916-9708- B	< 1			
25	ELIOT-HINE MIDDLE SCHOOL	5/13/2016	WS- 009692	Classroom	2	In art room 2-189 clockwise from window (3)	WT-042916-9709- A	77	WT-042916-9709- B	2.1	Filter will be installed and then retested		
26	ELIOT-HINE MIDDLE SCHOOL	5/13/2016	WS- 009693	Classroom	2	In art room 2-189 clockwise from window (2)	WT-042916-9710- A	7	WT-042916-9710- B	1.7			
27	ELIOT-HINE MIDDLE SCHOOL	5/13/2016	WS- 009694	Classroom	2	In art room 2-189 clockwise from window (1)	WT-042916-9711- A	5.5	WT-042916-9711- B	2.1			
28	ELIOT-HINE MIDDLE SCHOOL	5/13/2016	WS- 009695	Classroom	2	In room 2-188 clockwise from window (1)	WT-042916-9712- A	5.1	WT-042916-9712- B	< 1			
29	ELIOT-HINE MIDDLE SCHOOL	5/13/2016	WS- 009696	Classroom	2	In room 2-188 clockwise from window (2)	WT-042916-9713- A	2.9	WT-042916-9713- B	< 1			
30	ELIOT-HINE MIDDLE SCHOOL	5/13/2016	WS- 009697	Classroom	2	In room 2-188 clockwise from window (3)	WT-042916-9714- A	3.9	WT-042916-9714- B	< 1			
31	ELIOT-HINE MIDDLE SCHOOL	5/13/2016	WS- 009698	Classroom	2	In room 2-188 clockwise from window (4)	WT-042916-9715- A	2.7	WT-042916-9715- B	< 1			
32	ELIOT-HINE MIDDLE SCHOOL	5/13/2016	WS- 009699	Cooler	1	In first floor gymnasium across from male locker room	WT-042916-9716- A	< 1	WT-042916-9716- B	< 1			



# ELIOT-HINE LEAD WATER TEST RESULTS

May 24th, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
33	ELIOT-HINE MIDDLE SCHOOL	5/13/2016	WS- 009700	Cooler	3	In third floor girls locker room	WT-042916-9717- A	19	WT-042916-9717- B	23	Filter will be installed and then retested			

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.