



# FILMORE ARTS LEAD WATER TEST RESULTS



	Building Location: Building Name	RECORD ID	Date Analyzed	Floor	Device Type	Device Location			1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)
1	Filmore Arts Center (West)/Hardy MS	WS- 008763	8/20/2016	3	Cooler	In hallway across from classroom 302	High	Left	FT-82016-008763-A	< 1	FT-82016-008763-B	< 1
2	Filmore Arts Center (West)/Hardy MS	WS- 008764	8/20/2016	3	Cooler	In hallway across from classroom 302	Low	Right	FT-82016-008764-A	< 1	FT-82016-008764-B	< 1