



FORT DAVIS REC LEAD WATER TEST RESULTS May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1 FORT DAVIS RECREATION CENTER	5/25/2016	WS-005382	Utility	Basement	Main line in utility room	WT-042916-5399- A	225	WT-042916-5399- B	72.8	Non-drinking water source - Not accessible to children			
2 FORT DAVIS RECREATION CENTER	5/25/2016	WS-005383	Kitchen	Basement	In kitchen spray nozzle	WT-042916-5400- A	1.8	WT-042916-5400- B	< 1				
3 FORT DAVIS RECREATION CENTER	5/25/2016	WS-005384	Kitchen	Basement	In kitchen	WT-042916-5401- A	1.6	WT-042916-5401- B	< 1				
4 FORT DAVIS RECREATION CENTER	5/25/2016	WS-005385	Cooler	1	In hallway adjacent to room 103	WT-042916-5402- A	< 1	WT-042916-5402- B	< 1				
5 FORT DAVIS RECREATION CENTER	5/25/2016	WS-005386	Kitchen	1	In kitchen pantry 104	WT-042916-5403- A	< 1	WT-042916-5403- B	< 1				
6 FORT DAVIS RECREATION CENTER	5/25/2016	WS-005387	Fountain	Ground Floor	Exterior adjacent to picnic area	WT-042916-5404- A	< 1	WT-042916-5404- B	< 1				
7 FORT DAVIS RECREATION CENTER	5/25/2016	WS-005388	Fountain	Ground Floor	Exterior adjacent to picnic area	WT-042916-5405- A	< 1	WT-042916-5405- B	< 1				

Footnotes:

- A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.
- B - Second draw sample is collected after a 60 second flush at that device after the first draw.