



FORT STEVENS REC LEAD WATER TEST RESULTS May 16th, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1	FORT STEVENS RECREATION CENTER	5/25/2016	WS- 012685	Cooler	1	In hallway adjacent to dining area	WT-042916-12702- A	< 1	WT-042916-12702- B	< 1				
2	FORT STEVENS RECREATION CENTER	5/25/2016	WS- 012686	Utility	1	In boiler room located by double doors (water source)	WT-042916-12703- A	1.9	WT-042916-12703- B	< 1				
3	FORT STEVENS RECREATION CENTER	5/25/2016	WS- 012687	Classroom	1	In arts and crafts classroom	WT-042916-12704- A	< 1	WT-042916-12704- B	< 1				
4	FORT STEVENS RECREATION CENTER	5/25/2016	WS- 012688	Classroom	1	In dining room area	WT-042916-12705- A	< 1	WT-042916-12705- B	< 1				
5	FORT STEVENS RECREATION CENTER	5/25/2016	WS- 012689	Fountain	1	Water fountain playground side walkway Right High	WT-042916-12706- A	< 1	WT-042916-12706- B	< 1				
6	FORT STEVENS RECREATION CENTER	5/25/2016	WS- 012690	Fountain	1	Water fountain on playground side walkway Left Low	WT-042916-12707- A	< 1	WT-042916-12707- B	< 1				
7	FORT STEVENS RECREATION CENTER	5/25/2016	WS- 012691	Fountain	Ground Floor	Adjacent to the playground High	WT-042916-12708- A	< 1	WT-042916-12708- B	< 1				
8	FORT STEVENS RECREATION CENTER	5/25/2016	WS- 012694	Fountain	Ground Floor	Adjacent to the playground Low	WT-042916-12711- A	< 1	WT-042916-12711- B	< 1				

Footnotes:

- A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.
- B - Second draw sample is collected after a 60 second flush at that device after the first draw.