



# FRANCIS POOL LEAD WATER TEST RESULTS May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1 FRANCIS POOL	5/25/2016	WS- 011574	Health Suite	1	In health suite ( sink)	WT-042916-11591- A	< 1	WT-042916-11591- B	< 1				
2 FRANCIS POOL	5/25/2016	WS- 011575	Classroom	1	In room 102	WT-042916-11592- A	< 1	WT-042916-11592- B	< 1				
3 FRANCIS POOL	5/25/2016	WS- 011576	Cooler	1	In hallway adjacent to room 117 Right High	WT-042916-11593- A	< 1	WT-042916-11593- B	< 1				
4 FRANCIS POOL	5/25/2016	WS- 011577	Cooler	1	In hallway adjacent to room 117 Left Low	WT-042916-11594- A	< 1	WT-042916-11594- B	< 1				
5 FRANCIS POOL	5/25/2016	WS- 011578	Utility	1	In boiler room (water source)	WT-042916-11595- A	< 1	WT-042916-11595- B	< 1				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.