



# HENDLEY LEAD WATER TEST RESULTS

May 11th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest Results
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002799	Utility	Ground Floor	In water room G04	WT-042916-2816- A	3.6	WT-042916-2816- B	< 1			
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002800	Kitchen	Ground Floor	In kitchen facing south	WT-042916-2817- A	3.6	WT-042916-2817- B	< 1			
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002801	Kitchen	Ground Floor	In kitchen facing north	WT-042916-2818- A	< 1	WT-042916-2818- B	< 1			
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002802	Cooler	Ground Floor	In cafeteria beside kitchen entrance	WT-042916-2819- A	< 1	WT-042916-2819- B	< 1			
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002803	Cooler	Ground Floor	In hallway adjacent to book storage room G10	WT-042916-2820- A	< 1	WT-042916-2820- B	< 1			
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002804	Classroom	Ground Floor	In classroom G11	WT-042916-2821- A	< 1	WT-042916-2821- B	< 1			
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002805	Fountain	Ground Floor	In classroom G11	WT-042916-2822- A	< 1	WT-042916-2822- B	< 1			
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002806	Classroom	Ground Floor	In classroom G13	WT-042916-2823- A	< 1	WT-042916-2823- B	< 1			
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002807	Fountain	Ground Floor	In classroom G13	WT-042916-2824- A	< 1	WT-042916-2824- B	< 1			
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002808	Classroom	1	In classroom 110	WT-042916-2825- A	1.4	WT-042916-2825- B	< 1			
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002809	Fountain	1	In classroom 110	WT-042916-2826- A	< 1	WT-042916-2826- B	< 1			
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002810	Fountain	1	In classroom 108	Left	WT-042916-2827- A	< 1	WT-042916-2827- B	< 1		
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002811	Classroom	1	In classroom 108	Right	WT-042916-2828- A	< 1	WT-042916-2828- B	< 1		
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002812	Classroom	1	In classroom 107		WT-042916-2829- A	< 1	WT-042916-2829- B	< 1		
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002813	Fountain	1	In classroom 107		WT-042916-2830- A	< 1	WT-042916-2830- B	< 1		
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002814	Break Room	1	In break room 105		WT-042916-2831- A	< 1	WT-042916-2831- B	< 1		
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002815	Break Room	1	In break room 105 spray nozzle in sink		WT-042916-2832- A	< 1	WT-042916-2832- B	< 1		
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002816	Classroom	1	Health suite room 104	Mid	WT-042916-2833- A	< 1	WT-042916-2833- B	< 1		
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002817	Hose Bib	1	Health suite room 104		WT-042916-2834- A	1.3	WT-042916-2834- B	< 1		
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002818	Hose Bib	1	In parents resource room 103		WT-042916-2835- A	< 1	WT-042916-2835- B	< 1		
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002819	Break Room	1	In parent resource room 103 spray nozzle in sink		WT-042916-2836- A	1	WT-042916-2836- B	< 1		
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002820	Cooler	1	In hallway adjacent to resource room 109		WT-042916-2837- A	< 1	WT-042916-2837- B	< 1		
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002821	Cooler	2	In hallway adjacent to girls rest room	Left High	WT-042916-2838- A	< 1	WT-042916-2838- B	< 1		
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002822	Cooler	2	In hallway adjacent to girls restroom	Right Low	WT-042916-2839- A	< 1	WT-042916-2839- B	< 1		
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002823	Fountain	2	In hallway adjacent to room 201	Right	WT-042916-2840- A	< 1	WT-042916-2840- B	< 1		



# HENDLEY LEAD WATER TEST RESULTS

May 11th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest Results
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002824	Fountain	2	In hallway adjacent room 201 Left	WT-042916-2841- A	< 1	WT-042916-2841- B	< 1			
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002825	Fountain	3	In hallway adjacent to girls restroom	WT-042916-2842- A	< 1	WT-042916-2842- B	< 1			
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002826	Fountain	3	In hallway girls restroom	WT-042916-2843- A	< 1	WT-042916-2843- B	< 1			
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002827	Cooler	3	In hallway adjacent to boys restroom Left High	WT-042916-2844- A	< 1	WT-042916-2844- B	< 1			
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002828	Cooler	3	In hallway adjacent to boys restroom Right Low	WT-042916-2845- A	< 1	WT-042916-2845- B	< 1			
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002829	Cooler	Ground Floor	Annex, in hallway adjacent to classroom G17	WT-042916-2846- A	< 1	WT-042916-2846- B	< 1			
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002830	Classroom	Ground Floor	Annex, in classroom G17	WT-042916-2847- A	< 1	WT-042916-2847- B	< 1			
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002831	Fountain	Ground Floor	Annex, in classroom G17	WT-042916-2848- A	< 1	WT-042916-2848- B	< 1			
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002832	Fountain	Ground Floor	Annex, in classroom G16	WT-042916-2849- A	< 1	WT-042916-2849- B	< 1			
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002833	Classroom	Ground Floor	Annex, in classroom G16	WT-042916-2850- A	< 1	WT-042916-2850- B	< 1			
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002834	Fountain	Ground Floor	Annex, in classroom G14	WT-042916-2851- A	< 1	WT-042916-2851- B	< 1			
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002835	Classroom	Ground Floor	Annex, in classroom G14	WT-042916-2852- A	< 1	WT-042916-2852- B	< 1			
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002836	Classroom	Ground Floor	Annex, classroom G20	WT-042916-2853- A	11.3	WT-042916-2853- B	< 1			
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002837	Fountain	Ground Floor	Annex, classroom G20	WT-042916-2854- A	1.6	WT-042916-2854- B	< 1			
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002839	Classroom	1	Annex, classroom 118 Left	WT-042916-2856- A	< 1	WT-042916-2856- B	< 1			
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002840	Fountain	1	Annex, classroom 118 Right	WT-042916-2857- A	4.2	WT-042916-2857- B	< 1			
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002841	Classroom	1	Annex, classroom 118 Mid	WT-042916-2858- A	1	WT-042916-2858- B	< 1			
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002842	Fountain	1	Annex in classroom 118 Right	WT-042916-2859- A	4.9	WT-042916-2859- B	< 1			
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002843	Fountain	1	In classroom 118	WT-042916-2860- A	13.7	WT-042916-2860- B	< 1			
HENDLEY ELEMENTARY SCHOOL	5/4/2016	WS- 002844	Classroom	1	In classroom 118	WT-042916-2861- A	4.7	WT-042916-2861- B	< 1			

Footnotes:

- A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.
- B - Second draw sample is collected after a 60 second flush at that device after the first draw.