



# HILLCREST REC LEAD WATER TEST RESULTS

May 16th, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1	HILLCREST RECREATION CENTER	5/20/2016	WS- 005639	Cooler	1	In hallway adjacent to mechanical room 113 (revised water source)	WT-042916-5656- A	< 2	WT-042916-5656- B	< 2				
2	HILLCREST RECREATION CENTER	5/20/2016	WS- 005640	Cooler	1	In hallway across from gymnasium 100	WT-042916-5657- A	< 2	WT-042916-5657- B	< 2				
3	HILLCREST RECREATION CENTER	5/20/2016	WS- 005641	Kitchen	1	In kitchen - pantry room 102	WT-042916-5658- A	< 2	WT-042916-5658- B	< 2				
4	HILLCREST RECREATION CENTER	5/20/2016	WS- 005642	Classroom	1	In art and crafts room 107	WT-042916-5659- A	< 2	WT-042916-5659- B	< 2				
5	HILLCREST RECREATION CENTER	5/20/2016	WS- 005643	Fountain	Ground Floor	Exterior in playground	High WT-042916-5660- A	< 2	WT-042916-5660- B	< 2				
6	HILLCREST RECREATION CENTER	5/20/2016	WS- 005644	Fountain	Ground Floor	Exterior In playground	Low WT-042916-5661- A	< 2	WT-042916-5661- B	< 2				
7	HILLCREST RECREATION CENTER	5/20/2016	WS- 005645	Fountain	Ground Floor	Exterior facing playground	High WT-042916-5662- A	< 2	WT-042916-5662- B	< 2				
8	HILLCREST RECREATION CENTER	5/20/2016	WS- 005646	Fountain	Ground Floor	Exterior facing playground	Low WT-042916-5663- A	< 2	WT-042916-5663- B	< 2				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.