



HOUSTON LEAD WATER TEST RESULTS

May 24th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
HOUSTON ELEMENTARY SCHOOL	5/12/2016	WS- 009340	Utility	Basement	In boiler room (tub sink)	WT-042916-9357- A	< 2	WT-042916-9357- B	< 2				
HOUSTON ELEMENTARY SCHOOL	5/12/2016	WS- 009341	Classroom	1	In multipurpose room	WT-042916-9358- A	< 2	WT-042916-9358- B	< 2				
HOUSTON ELEMENTARY SCHOOL	5/12/2016	WS- 009342	Kitchen	1	In kitchen Left	WT-042916-9359- A	< 2	WT-042916-9359- B	< 2				
HOUSTON ELEMENTARY SCHOOL	5/12/2016	WS- 009343	Kitchen	1	In kitchen Right	WT-042916-9360- A	< 2	WT-042916-9360- B	< 2				
HOUSTON ELEMENTARY SCHOOL	5/12/2016	WS- 009344	Kitchen	1	In kitchen dish washing area Right	WT-042916-9361- A	113	WT-042916-9361- B	13	Filter will be installed and then retested			
HOUSTON ELEMENTARY SCHOOL	5/12/2016	WS- 009345	Cooler	1	In hallway across teachers lounge	WT-042916-9362- A	< 2	WT-042916-9362- B	< 2				
HOUSTON ELEMENTARY SCHOOL	5/12/2016	WS- 009346	Cooler	1	Teachers lounge	WT-042916-9363- A	5	WT-042916-9363- B	4.3				
HOUSTON ELEMENTARY SCHOOL	5/12/2016	WS- 009347	Break Room	1	In teacher's lounge	WT-042916-9364- A	< 2	WT-042916-9364- B	< 2				
HOUSTON ELEMENTARY SCHOOL	5/12/2016	WS- 009348	Classroom	1	Water sink classroom 145	WT-042916-9365- A	4.6	WT-042916-9365- B	< 2				
HOUSTON ELEMENTARY SCHOOL	5/12/2016	WS- 009349	Classroom	1	In classroom 145 adjacent to the door	WT-042916-9366- A	5.3	WT-042916-9366- B	< 2				
HOUSTON ELEMENTARY SCHOOL	5/12/2016	WS- 009350	Classroom	1	Hand washing sink in classroom 146	WT-042916-9367- A	10.4	WT-042916-9367- B	< 2				
HOUSTON ELEMENTARY SCHOOL	5/12/2016	WS- 009351	Cooler	1	In classroom 147	WT-042916-9368- A	< 2	WT-042916-9368- B	< 2				
HOUSTON ELEMENTARY SCHOOL	5/12/2016	WS- 009352	Classroom	1	In classroom 147	WT-042916-9369- A	< 2	WT-042916-9369- B	< 2				
HOUSTON ELEMENTARY SCHOOL	5/12/2016	WS- 009353	Fountain	1	In classroom 148	WT-042916-9370- A	< 2	WT-042916-9370- B	< 2				
HOUSTON ELEMENTARY SCHOOL	5/12/2016	WS- 009354	Classroom	1	In classroom 148	WT-042916-9371- A	< 2	WT-042916-9371- B	< 2				
HOUSTON ELEMENTARY SCHOOL	5/12/2016	WS- 009355	Cooler	1	In hallway adjacent to classroom 156	WT-042916-9372- A	< 2	WT-042916-9372- B	< 2				
HOUSTON ELEMENTARY SCHOOL	5/12/2016	WS- 009356	Cooler	1	In hallway Adjacent to girls restroom	WT-042916-9373- A	< 2	WT-042916-9373- B	< 2				
HOUSTON ELEMENTARY SCHOOL	5/12/2016	WS- 009357	Health Suite	1	In health suite	WT-042916-9374- A	< 2	WT-042916-9374- B	< 2				
HOUSTON ELEMENTARY SCHOOL	5/12/2016	WS- 009658	Health Suite	1	In health suite in bathroom	WT-042916-9675- A	< 2	WT-042916-9675- B	< 2				
HOUSTON ELEMENTARY SCHOOL	5/12/2016	WS- 009659	Cooler	1	In hallway adjacent to 112	WT-042916-9676- A	< 2	WT-042916-9676- B	< 2				
HOUSTON ELEMENTARY SCHOOL	5/12/2016	WS- 009660	Cooler	2	In hallway across to classroom 209. Adjacent to room 212	WT-042916-9677- A	< 2	WT-042916-9677- B	< 2				
HOUSTON ELEMENTARY SCHOOL	5/12/2016	WS- 009661	Cooler	2	In hallway adjacent to girls bathroom	WT-042916-9678- A	< 2	WT-042916-9678- B	< 2				
HOUSTON ELEMENTARY SCHOOL	5/12/2016	WS- 009663	Classroom	1	In classroom 114	WT-042916-9680- A	79.9	WT-042916-9680- B	8	Filter will be installed and then retested			

Footnotes:

- A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.
- B - Second draw sample is collected after a 60 second flush at that device after the first draw.