



# JOHNSON LEAD WATER TEST RESULTS

May 24th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1 Johnson MS	5/14/2016	WS- 011102	Utility	Basement	In boiler room; main water supply. Sink.	WT-042916-11119- A	1	WT-042916-11119- B	< 1				
2 Johnson MS	5/14/2016	WS- 011103	Kitchen	Ground Floor	In southwall Left	WT-042916-11120- A	12.9	WT-042916-11120- B	10.9	Filter will be installed and then retested			
3 Johnson MS	5/14/2016	WS- 011104	Kitchen	Ground Floor	In southwall Right	WT-042916-11121- A	110	WT-042916-11121- B	22.4	Filter will be installed and then retested			
4 Johnson MS	5/14/2016	WS- 011105	Kitchen	Ground Floor	In south wall adjacent office	WT-042916-11122- A	< 1	WT-042916-11122- B	< 1				
5 Johnson MS	5/14/2016	WS- 011106	Kitchen	Ground Floor	In eastwall Right	WT-042916-11123- A	2.2	WT-042916-11123- B	< 1				
6 Johnson MS	5/14/2016	WS- 011107	Kitchen	Ground Floor	In kitchen C001 east wall left	WT-042916-11124- A	< 1	WT-042916-11124- B	< 1				
7 Johnson MS	5/14/2016	WS- 011108	Kitchen	Ground Floor	In kitchen North wall	WT-042916-11125- A	2.4	WT-042916-11125- B	< 1				
8 Johnson MS	5/14/2016	WS- 011109	Kitchen	Ground Floor	In kitchen C001 south wall ice machine	WT-042916-11126- A	< 1	WT-042916-11126- B	< 1				
9 Johnson MS	5/14/2016	WS- 011110	Cooler	Ground Floor	In cafeteria east wall	WT-042916-11127- A	< 1	WT-042916-11127- B	< 1				
10 Johnson MS	5/14/2016	WS- 011111	Cooler	Ground Floor	In cafeteria westwall	WT-042916-11128- A	< 1	WT-042916-11128- B	< 1				
11 Johnson MS	5/14/2016	WS- 011112	Cooler	1	In hallway adjacent to gym	WT-042916-11129- A	< 1	WT-042916-11129- B	< 1				
12 Johnson MS	5/14/2016	WS- 011113	Health Suite	1	In health suite treatment room 111B	WT-042916-11130- A	< 1	WT-042916-11130- B	< 1				
13 Johnson MS	5/14/2016	WS- 011114	Classroom	1	In classroom 114 adjacent to classroom 114a	WT-042916-11131- A	< 1	WT-042916-11131- B	< 1				
14 Johnson MS	5/14/2016	WS- 011115	Break Room	1	In break room 107	WT-042916-11132- A	< 1	WT-042916-11132- B	< 1				
15 Johnson MS	5/14/2016	WS- 011116	Cooler	1	In hallway adjacent to room 111	WT-042916-11133- A	< 1	WT-042916-11133- B	< 1				
16 Johnson MS	5/14/2016	WS- 011117	Cooler	1	In hallway adjacent to auditorium	WT-042916-11134- A	< 1	WT-042916-11134- B	< 1				
17 Johnson MS	5/14/2016	WS- 011118	Cooler	1	In girl locker room	WT-042916-11135- A	< 1	WT-042916-11135- B	< 1				
18 Johnson MS	5/14/2016	WS- 011119	Cooler	2	In hallway adjacent to room 225A Left High	WT-042916-11136- A	< 1	WT-042916-11136- B	< 1				
19 Johnson MS	5/14/2016	WS- 011120	Cooler	2	In hallway adjacent to room 225A Right Low	WT-042916-11137- A	< 1	WT-042916-11137- B	< 1				
20 Johnson MS	5/14/2016	WS- 011121	Cooler	2	In hallway adjacent room 204	WT-042916-11138- A	< 1	WT-042916-11138- B	< 1				
21 Johnson MS	5/14/2016	WS- 011122	Cooler	2	In hallway adjacent to room 220 Left High	WT-042916-11139- A	< 1	WT-042916-11139- B	< 1				
22 Johnson MS	5/14/2016	WS- 011123	Cooler	2	In hallway adjacent room 220 Right Low	WT-042916-11140- A	< 1	WT-042916-11140- B	< 1				
23 Johnson MS	5/14/2016	WS- 011124	Classroom	2	In classroom 220 (Sink 1)	WT-042916-11141- A	< 1	WT-042916-11141- B	< 1				
24 Johnson MS	5/14/2016	WS- 011125	Classroom	2	In classroom 220 (sink2)	WT-042916-11142- A	1.3	WT-042916-11142- B	< 1				
25 Johnson MS	5/14/2016	WS- 011126	Classroom	2	In classroom 220 (sink 3)	WT-042916-11143- A	2.4	WT-042916-11143- B	1.1				
26 Johnson MS	5/14/2016	WS- 011127	Classroom	2	In classroom 220 (sink 4)	WT-042916-11144- A	3.3	WT-042916-11144- B	1.3				
27 Johnson MS	5/14/2016	WS- 011128	Classroom	2	In classroom 220 (sink 5)	WT-042916-11145- A	2.4	WT-042916-11145- B	2.1				
28 Johnson MS	5/14/2016	WS- 011129	Classroom	2	In room 220 (sink 6)	WT-042916-11146- A	2.2	WT-042916-11146- B	1				
29 Johnson MS	5/14/2016	WS- 011130	Classroom	2	In room 220 (Sink 7)	WT-042916-11147- A	2.8	WT-042916-11147- B	1				
30 Johnson MS	5/14/2016	WS- 011131	Classroom	2	In room 220 (Sink 8)	WT-042916-11148- A	15.9	WT-042916-11148- B	1.6	Filter will be installed and then retested			
31 Johnson MS	5/14/2016	WS- 011133	Cooler	3	In hallway adjacent to room 315A Left High	WT-042916-11150- A	< 1	WT-042916-11150- B	< 1				
32 Johnson MS	5/14/2016	WS- 011134	Cooler	3	In hallway adjacent to room 315A Low	WT-042916-11151- A	< 1	WT-042916-11151- B	< 1				
33 Johnson MS	5/14/2016	WS- 011135	Classroom	3	In classroom 318 east wall Left	WT-042916-11152- A	17.1	WT-042916-11152- B	2.2	Filter will be installed and then retested			
34 Johnson MS	5/14/2016	WS- 011136	Classroom	3	In classroom 318 east wall middle left	WT-042916-11153- A	46.8	WT-042916-11153- B	7.4	Filter will be installed and then retested			
35 Johnson MS	5/14/2016	WS- 011137	Classroom	3	In classroom 326B east wall Mid	WT-042916-11154- A	16.2	WT-042916-11154- B	6.9	Filter will be installed and then retested			
36 Johnson MS	5/14/2016	WS- 011138	Classroom	3	In classroom 318 north wall Left	WT-042916-11155- A	92.1	WT-042916-11155- B	40	Filter will be installed and then retested			
37 Johnson MS	5/14/2016	WS- 011139	Classroom	3	In classroom 318 left/mid Left	WT-042916-11156- A	10.6	WT-042916-11156- B	4				



# JOHNSON LEAD WATER TEST RESULTS

May 24th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
38 Johnson MS	5/14/2016	WS- 011140	Classroom	3	In room 318 Mid	WT-042916-11157- A	14.9	WT-042916-11157- B	2.3	Filter will be installed and then retested			
39 Johnson MS	5/14/2016	WS- 011141	Classroom	3	In room 318, north wall right/mid Right	WT-042916-11158- A	44.5	WT-042916-11158- B	2.9	Filter will be installed and then retested			
40 Johnson MS	5/14/2016	WS- 011142	Classroom	3	In room room 318/ North wall Right	WT-042916-11159- A	8.7	WT-042916-11159- B	5.2				
41 Johnson MS	5/14/2016	WS- 011143	Classroom	3	In room 318	WT-042916-11160- A	7.5	WT-042916-11160- B	1.1				
42 Johnson MS	5/14/2016	WS- 011144	Cooler	3	In hallway adjacent room 323 High	WT-042916-11161- A	< 1	WT-042916-11161- B	< 1				
43 Johnson MS	5/14/2016	WS- 011145	Cooler	3	In hallway adjacent room 323 Right Low	WT-042916-11162- A	< 1	WT-042916-11162- B	< 1				
44 Johnson MS	5/14/2016	WS- 011146	Cooler	3	In hallway adjacent to room 326A	WT-042916-11163- A	< 1	WT-042916-11163- B	< 1				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.