



# JOY EVANS REC LEAD WATER TEST RESULTS

May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1 JOY EVANS RECREATION CENTER	5/26/2016	WS- 006395	Other	Ground Floor	Pool house Boiler room on east wall	WT-042916-6412- A	1	WT-042916-6412- B	< 1				
2 JOY EVANS RECREATION CENTER	5/26/2016	WS- 006396	Fountain	Ground Floor	On north wall adjacent to men's room .	WT-042916-6413- A	2	WT-042916-6413- B	< 1				
3 JOY EVANS RECREATION CENTER	5/26/2016	WS- 006397	Cooler	Ground Floor	In foyer on east wall adjacent to fountain	WT-042916-6414- A	8.4	WT-042916-6414- B	3.2				
4 JOY EVANS RECREATION CENTER	5/26/2016	WS- 006398	Fountain	Ground Floor	On foyer east wall adjacent to cooler	WT-042916-6415- A	44	WT-042916-6415- B	12	Filter will be installed and then retested			
5 JOY EVANS RECREATION CENTER	5/26/2016	WS- 006399	Other	Ground Floor	In office on east wall (sink)	WT-042916-6416- A	4.8	WT-042916-6416- B	< 1				
6 JOY EVANS RECREATION CENTER	5/26/2016	WS- 006400	Other	Ground Floor	In custodial room on north wall	WT-042916-6417- A	150	WT-042916-6417- B	4.6	Non-drinking water source - Not accessible to children			
7 JOY EVANS RECREATION CENTER	5/26/2016	WS- 006401	Kitchen	Ground Floor	In kitchen west wall(sink)	WT-042916-6418- A	2.7	WT-042916-6418- B	< 1				

Footnotes:

- A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.
- B - Second draw sample is collected after a 60 second flush at that device after the first draw.