



KENNEDY REC LEAD WATER TEST RESULTS

May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1 KENNEDY REC CTR	5/19/2016	WS- 005630	Cooler	1	In hallway adjacent to room 128 'janitors closet'	WT-042916-5647- A	< 2	WT-042916-5647- B	< 2				
2 KENNEDY REC CTR	5/19/2016	WS- 005631	Kitchen	1	In kitchen	WT-042916-5648- A	< 2	WT-042916-5648- B	< 2				
3 KENNEDY REC CTR	5/19/2016	WS- 005632	Fountain	Ground Floor	Exterior adjacent to playground and basketball court	High WT-042916-5649- A	< 2	WT-042916-5649- B	< 2				
4 KENNEDY REC CTR	5/19/2016	WS- 005633	Fountain	Ground Floor	Exterior facing basketball court	Low WT-042916-5650- A	< 2	WT-042916-5650- B	< 2				
5 KENNEDY REC CTR	5/19/2016	WS- 005634	Fountain	Ground Floor	Exterior clockwise adjacent to playground (2)	Low WT-042916-5651- A	< 2	WT-042916-5651- B	< 2				
6 KENNEDY REC CTR	5/19/2016	WS- 005635	Fountain	Ground Floor	Exterior clockwise adjacent to playground 2	High WT-042916-5652- A	< 2	WT-042916-5652- B	< 2				
7 KENNEDY REC CTR	5/19/2016	WS- 005636	Fountain	Ground Floor	Exterior clockwise (3) facing tennis court	Low WT-042916-5653- A	< 2	WT-042916-5653- B	< 2				
8 KENNEDY REC CTR	5/19/2016	WS- 005637	Fountain	Ground Floor	Exterior clockwise (3) facing tennis court	High WT-042916-5654- A	< 2	WT-042916-5654- B	< 2				

Footnotes:

- A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.
- B - Second draw sample is collected after a 60 second flush at that device after the first draw.