



# KING GREENLEAF REC LEAD WATER TEST RESULTS



	Building Location: Building Name	RECORD ID	Date Analyzed	Floor	Device Type	Device Location			1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)
1	KING GREENLEAF RECREATION CENTER	WS- 012000	9/22/2016	Ground Floor	Cooler	In hallway adjacent to janitors' closet	Low	Left	FT-82016-012000-A	< 1	FT-82016-012000-B	< 1
2	KING GREENLEAF RECREATION CENTER	WS- 012001	9/22/2016	Ground Floor	Cooler	In hallway adjacent to janitors' closet	High	Right	FT-82016-012001-A	< 1	FT-82016-012001-B	< 1
3	KING GREENLEAF RECREATION CENTER	WS- 012002	9/22/2016	Ground Floor	Food Prep Sink	In kitchen			FT-82016-012002-A	< 1	FT-82016-012002-B	< 1