



LACASA THERAPEUTIC LEAD WATER TEST RESULTS May 16th, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1	LACASA THERAPEUTIC PROGRAM	5/26/2016	WS- 005671	Utility	1	In laundry room, in closet (water source)	WT-042916-5688- A	4	WT-042916-5688- B	< 1				
2	LACASA THERAPEUTIC PROGRAM	5/27/2016	WS- 005672	Cooler	2	In hallway adjacent to room 204	WT-042916-5689- A	< 1	WT-042916-5689- B	< 1				
3	LACASA THERAPEUTIC PROGRAM	5/26/2016	WS- 005673	Cooler	3	In hallway adjacent to room 308	WT-042916-5690- A	< 1	WT-042916-5690- B	< 1				
4	LACASA THERAPEUTIC PROGRAM	5/27/2016	WS- 005674	Other	2	In kitchen adjacent to stove (spray nozzle)	WT-042916-5691- A	< 1	WT-042916-5691- B	< 1				
5	LACASA THERAPEUTIC PROGRAM	5/27/2016	WS- 005675	Kitchen	2	In kitchen	WT-042916-5692- A	< 1	WT-042916-5692- B	1.3				

Footnotes:

- A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.
- B - Second draw sample is collected after a 60 second flush at that device after the first draw.