



# MACOMB REC LEAD WATER TEST RESULTS

May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1 MACOMB RECREATION CENTER	5/27/2016	WS-012697	Utility	1	In men's bathroom utility sink (water source)	WT-042916-12714-A	< 1	WT-042916-12714-B	< 1				
2 MACOMB RECREATION CENTER	5/27/2016	WS-012698	Fountain	1	Inside rec center middle of room	WT-042916-12715-A	< 1	WT-042916-12715-B	< 1				
3 MACOMB RECREATION CENTER	5/27/2016	WS-012699	Fountain	1	Inside rec center middle of room	WT-042916-12716-A	< 1	WT-042916-12716-B	< 1				
4 MACOMB RECREATION CENTER	5/27/2016	WS-012700	Fountain	1	Exterior walkway of playground	WT-042916-12717-A	< 1	WT-042916-12717-B	< 1				
5 MACOMB RECREATION CENTER	5/27/2016	WS-012701	Fountain	1	Exterior walkway by playground	WT-042916-12718-A	< 1	WT-042916-12718-B	< 1				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.