



MAURY ES LEAD WATER TEST RESULTS



Initial Filter Test After Installation

	Building Location: Building Name	RECORD ID	Date Analyzed	Floor	Device Type	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	Final Result - 2nd Draw (ppb)	
1	MAURY ELEMENTARY SCHOOL	WS- 008481	12/11/2016	1	Break Room	In work room E134	Left	FT-112016-008481-A	< 1	FT-112016-008481-B	< 1
2	MAURY ELEMENTARY SCHOOL	WS- 008496	12/11/2016	2	Break Room	In break room E235	Left	FT-112016-008496-A	< 1	FT-112016-008496-B	< 1
3	MAURY ELEMENTARY SCHOOL	WS- 008498	12/11/2016	2	Combo Faucet	In classroom E240	Left	FT-112016-008498-A	< 1	FT-112016-008498-B	< 1
4	MAURY ELEMENTARY SCHOOL	WS- 008495	12/11/2016	2	Combo Faucet	In classroom E230	Left	FT-112016-008495-A	< 1	FT-112016-008495-B	< 1
5	MAURY ELEMENTARY SCHOOL	WS- 008477	12/11/2016	1	Combo Faucet	In classroom E 135	Left	FT-112016-008477-A	< 1	FT-112016-008477-B	< 1
6	MAURY ELEMENTARY SCHOOL	WS- 008492	12/11/2016	2	Classroom Faucet	In classroom E220	Left	FT-112016-008492-A	< 1	FT-112016-008492-B	< 1
7	MAURY ELEMENTARY SCHOOL	WS- 008493	12/11/2016	2	Classroom Faucet	In classroom E220	Right	FT-112016-008493-A	< 1	FT-112016-008493-B	< 1
8	MAURY ELEMENTARY SCHOOL	WS- 008474	12/11/2016	Basement	Combo Faucet	In classroom W010	Left	FT-112016-008474-A	< 1	FT-112016-008474-B	< 1
9	MAURY ELEMENTARY SCHOOL	WS- 008480	12/11/2016	1	Combo Faucet	In classroom E140	Left	FT-112016-008480-A	< 1	FT-112016-008480-B	< 1
10	MAURY ELEMENTARY SCHOOL	WS- 008483	12/11/2016	1	Combo Faucet	In classroom E125	Left	FT-112016-008483-A	< 1	FT-112016-008483-B	< 1
11	MAURY ELEMENTARY SCHOOL	WS- 008470	12/11/2016	Basement	Combo Faucet	In classroom W030	Left	FT-112016-008470-A	< 1	FT-112016-008470-B	< 1

Note :

Filter re-tests are only performed to devices that have sampling results greater than 1 ppb