



NORTH MICHIGAN LEAD WATER TEST RESULTS May 16th, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1	NORTH MICHIGAN PARK REC	5/21/2016	WS- 011555	Utility	1	In boiler room (water source)	WT-042916-11572- A	32	WT-042916-11572- B	12	Non-drinking water source - Not accessible to children			
2	NORTH MICHIGAN PARK REC	5/21/2016	WS- 011556	Cooler	1	In hallway adjacent to women restroom Left Low	WT-042916-11573- A	< 1	WT-042916-11573- B	< 1				
3	NORTH MICHIGAN PARK REC	5/21/2016	WS- 011557	Cooler	1	In hallway adjacent to women restroom Right High	WT-042916-11574- A	< 1	WT-042916-11574- B	< 1				
4	NORTH MICHIGAN PARK REC	5/21/2016	WS- 011558	Cooler	1	In hallway adjacent to room 104 Left High	WT-042916-11575- A	< 1	WT-042916-11575- B	< 1				
5	NORTH MICHIGAN PARK REC	5/21/2016	WS- 011559	Cooler	1	In hallway adjacent to room 104 Right Low	WT-042916-11576- A	< 1	WT-042916-11576- B	< 1				
6	NORTH MICHIGAN PARK REC	5/21/2016	WS- 011560	Kitchen	1	In kitchen (107)	WT-042916-11577- A	1.2	WT-042916-11577- B	< 1				
7	NORTH MICHIGAN PARK REC	5/21/2016	WS- 011561	Kitchen	1	In kitchen	WT-042916-11578- A	< 1	WT-042916-11578- B	< 1				

Footnotes:

- A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.
- B - Second draw sample is collected after a 60 second flush at that device after the first draw.