



# ORR ES LEAD WATER TEST RESULTS



## Initial Filter Test After Installation

	Building Location: Building Name	RECORD ID	Date Analyzed	Floor	Device Type	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	Final Result - 2nd Draw (ppb)
1	ORR ELEMENTARY SCHOOL	WS- 009832	12/21/2016	2	Classroom Faucet	In classroom Kindergarten third clockwise around res Left	FT-122016-009832-A	< 1	FT-122016-009832-B	< 1
2	ORR ELEMENTARY SCHOOL	WS- 009821	12/21/2016	1	Classroom Faucet	In classroom Pre-K3 second clockwise around restroc Right	FT-122016-009821-A	< 1	FT-122016-009821-B	< 1
3	ORR ELEMENTARY SCHOOL	WS- 009824	12/21/2016	1	Classroom Faucet	In classroom Pre-K3 south section fifth clockwise aroi Right	FT-122016-009824-A	< 1	FT-122016-009824-B	< 1
4	ORR ELEMENTARY SCHOOL	WS- 009825	12/21/2016	1	Classroom Faucet	In classroom Pre-K3 south section fourth clockwise ai Left	FT-122016-009825-A	< 1	FT-122016-009825-B	< 1
5	ORR ELEMENTARY SCHOOL	WS- 009829	12/21/2016	1	Classroom Faucet	In classroom Pre-K3 south section second clockwise a Right	FT-122016-009829-A	< 1	FT-122016-009829-B	< 1
6	ORR ELEMENTARY SCHOOL	WS- 009830	12/21/2016	1	Classroom Faucet	In classroom Pre-K3 south section first clockwise aroi Left	FT-122016-009830-A	< 1	FT-122016-009830-B	< 1
7	ORR ELEMENTARY SCHOOL	WS- 009818	12/21/2016	1	Classroom Faucet	In classroom Pre-K3 fourth clockwise around restroor Left	FT-122016-009818-A	< 1	FT-122016-009818-B	< 1
8	ORR ELEMENTARY SCHOOL	WS- 009835	12/21/2016	2	Classroom Faucet	In classroom Kindergarten second clockwise around r Right	FT-122016-009835-A	< 1	FT-122016-009835-B	< 1
9	ORR ELEMENTARY SCHOOL	WS- 009833	12/21/2016	2	Classroom Faucet	In classroom Kindergarten fourth clockwise around r Right	FT-122016-009833-A	< 1	FT-122016-009833-B	< 1
10	ORR ELEMENTARY SCHOOL	WS- 009822	12/21/2016	1	Classroom Faucet	In classroom Pre-K3 first clockwise around restrooms Left	FT-122016-009822-A	< 1	FT-122016-009822-B	< 1
11	ORR ELEMENTARY SCHOOL	WS- 009834	12/21/2016	2	Classroom Faucet	In classroom Kindergarten first clockwise around rest Left	FT-122016-009834-A	< 1	FT-122016-009834-B	< 1
12	ORR ELEMENTARY SCHOOL	WS- 009817	12/21/2016	1	Classroom Faucet	In classroom Pre-K3 fifth clockwise around restrooms Right	FT-122016-009817-A	< 1	FT-122016-009817-B	< 1

Note :

Filter re-tests are only performed to devices that have sampling results greater than 1 ppb