



PARKVIEW REC LEAD WATER TEST RESULTS



	Building Location: Building Name	RECORD ID	Date Analyzed	Floor	Device Type	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)
1	PARKVIEW REC CTR	WS- 011988	9/22/2016	Ground Floor	Cooler	In multipurpose room adjacent to women's restroom	FT-82016-011988-A	< 1	FT-82016-011988-B	< 1
2	PARKVIEW REC CTR	WS- 011990	9/22/2016	Ground Floor	Food Prep Sink	In kitchen	FT-82016-011990-A	< 1	FT-82016-011990-B	< 1
3	PARKVIEW REC CTR	WS- 011991	9/22/2016	Ground Floor	Cooler	In multipurpose room adjacent to front desk	FT-82016-011991-A	< 1	FT-82016-011991-B	< 1