



PETWORTH REC LEAD WATER TEST RESULTS

May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1 PETWORTH RECREATION CENTER	5/27/2016	WS- 005392	Kitchen	1	In kitchen	WT-042916-5409- A	< 1	WT-042916-5409- B	< 1				
2 PETWORTH RECREATION CENTER	5/27/2016	WS- 005393	Cooler	1	In main hall	WT-042916-5410- A	< 1	WT-042916-5410- B	< 1				
3 PETWORTH RECREATION CENTER	5/27/2016	WS- 005394	Fountain	Ground Floor	Exterior adjacent to play ground	WT-042916-5411- A	< 1	WT-042916-5411- B	< 1				
4 PETWORTH RECREATION CENTER	5/27/2016	WS- 005395	Fountain	Ground Floor	Exterior adjacent to play ground	WT-042916-5412- A	< 1	WT-042916-5412- B	< 1				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.