



# RIGGS LASALLE REC LEAD WATER TEST RESULTS May 16th, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1	RIGGS LASALLE RECREATION CENTER	5/21/2016	WS- 012015	Bathroom	1	In women's restroom (water source)	WT-042916-12032- A	< 1	WT-042916-12032- B	< 1				
2	RIGGS LASALLE RECREATION CENTER	5/21/2016	WS- 012016	Cooler	1	In hallway in between restrooms Left Low	WT-042916-12033- A	< 1	WT-042916-12033- B	< 1				
3	RIGGS LASALLE RECREATION CENTER	5/21/2016	WS- 012017	Cooler	1	In hallway in between restrooms Right High	WT-042916-12034- A	< 1	WT-042916-12034- B	< 1				
4	RIGGS LASALLE RECREATION CENTER	5/21/2016	WS- 012018	Classroom	1	In arts and crafts room 106	WT-042916-12035- A	< 1	WT-042916-12035- B	< 1				
5	RIGGS LASALLE RECREATION CENTER	5/21/2016	WS- 012019	Kitchen	1	In kitchen room 107	WT-042916-12036- A	< 1	WT-042916-12036- B	< 1				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.