



ROSEDALE REC LEAD WATER TEST RESULTS

May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1	ROSEDALE REC CTR	5/19/2016	WS-011528	Kitchen	1	In kitchen room 119	Left	WT-042916-11545-A	< 2	WT-042916-11545-B	< 2		
2	ROSEDALE REC CTR	5/19/2016	WS-011529	Other	1	In kitchen room 119 (spray nozzle)	Right	WT-042916-11546-A	< 2	WT-042916-11546-B	< 2		
3	ROSEDALE REC CTR	5/19/2016	WS-011530	Cooler	1	In hallway adjacent to office 102	Left High	WT-042916-11547-A	< 2	WT-042916-11547-B	< 2		
4	ROSEDALE REC CTR	5/19/2016	WS-011531	Cooler	1	In hallway adjacent to office 102	Right Low	WT-042916-11548-A	< 2	WT-042916-11548-B	< 2		
5	ROSEDALE REC CTR	5/19/2016	WS-011532	Classroom	1	In room 104	Left	WT-042916-11549-A	< 2	WT-042916-11549-B	< 2		
6	ROSEDALE REC CTR	5/19/2016	WS-011533	Other	1	In room 104 (spray nozzle)	Right	WT-042916-11550-A	< 2	WT-042916-11550-B	< 2		
7	ROSEDALE REC CTR	5/19/2016	WS-011534	Kitchen	1	In kitchen 106	Left	WT-042916-11551-A	< 2	WT-042916-11551-B	< 2		
8	ROSEDALE REC CTR	5/19/2016	WS-011535	Other	1	In kitchen 106 (spray nozzle)	Left	WT-042916-11552-A	< 2	WT-042916-11552-B	< 2		
9	ROSEDALE REC CTR	5/19/2016	WS-011536	Kitchen	1	In kitchen 106	Right	WT-042916-11553-A	3.2	WT-042916-11553-B	< 2		
10	ROSEDALE REC CTR	5/19/2016	WS-011537	Other	1	In kitchen 106 (spray nozzle)	Right	WT-042916-11554-A	< 2	WT-042916-11554-B	< 2		
11	ROSEDALE REC CTR	5/19/2016	WS-011538	Cooler	Ground Floor	Exterior in pool area adjacent to 122 (gymnasium)	Left High	WT-042916-11555-A	< 2	WT-042916-11555-B	< 2		
12	ROSEDALE REC CTR	5/19/2016	WS-011539	Utility	Ground Floor	Exterior in pool area adjacent to 122 (gymnasium) spigot (water source)		WT-042916-11556-A	3.3	WT-042916-11556-B	< 2		
13	ROSEDALE REC CTR	5/19/2016	WS-011540	Cooler	Ground Floor	Exterior in pool area adjacent to 122 (gymnasium)	Right Low	WT-042916-11557-A	< 2	WT-042916-11557-B	< 2		
14	ROSEDALE REC CTR	5/19/2016	WS-011541	Cooler	1	In library		WT-042916-11558-A	< 2	WT-042916-11558-B	< 2		
15	ROSEDALE REC CTR	5/19/2016	WS-011542	Classroom	1	In work room (library)	Left	WT-042916-11559-A	< 2	WT-042916-11559-B	< 2		
16	ROSEDALE REC CTR	5/19/2016	WS-011543	Other	1	In work room (library, spray nozzle)	Right	WT-042916-11560-A	< 2	WT-042916-11560-B	< 2		
17	ROSEDALE REC CTR	5/19/2016	WS-011544	Fountain	Ground Floor	Exterior in play ground area		WT-042916-11561-A	< 2	WT-042916-11561-B	< 2		

Footnotes:

- A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.
- B - Second draw sample is collected after a 60 second flush at that device after the first draw.