



SOUTHEAST TENNIS LEAD WATER TEST RESULTS May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1 SOUTHEAST TENNIS & LEARNING CENTER	5/21/2016	WS- 005647	Utility	1	In mechanical closet room 104 in conference room 106 (water source)	WT-042916-5664- A	250	WT-042916-5664- B	5.6	Non-drinking water source - Not accessible to children			
2 SOUTHEAST TENNIS & LEARNING CENTER	5/21/2016	WS- 005648	Cooler	1	In hallway adjacent to girls bathroom	WT-042916-5665- A	< 1	WT-042916-5665- B	< 1				
3 SOUTHEAST TENNIS & LEARNING CENTER	5/21/2016	WS- 005649	Other	1	In kitchen (ice maker)	WT-042916-5666- A	2.8	WT-042916-5666- B	1.8				
4 SOUTHEAST TENNIS & LEARNING CENTER	5/21/2016	WS- 005650	Kitchen	1	In kitchen	WT-042916-5667- A	< 1	WT-042916-5667- B	< 1				
5 SOUTHEAST TENNIS & LEARNING CENTER	5/21/2016	WS- 005651	Cooler	1	In hallway adjacent to men staff bathroom (reception area) Low	WT-042916-5668- A	< 1	WT-042916-5668- B	< 1				
6 SOUTHEAST TENNIS & LEARNING CENTER	5/21/2016	WS- 005652	Cooler	1	In hallway adjacent to women staff bathroom (reception area) High	WT-042916-5669- A	< 1	WT-042916-5669- B	< 1				
7 SOUTHEAST TENNIS & LEARNING CENTER	5/21/2016	WS- 005653	Fountain	Ground Floor	Exterior facing tennis courts adjacent to gym	WT-042916-5670- A	< 1	WT-042916-5670- B	< 1				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.